<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action OPERATOR Division Report M. Final Report													
			OPERA'			Initia	al Report	\boxtimes	Final Report				
Name of Co		Contact: Courtney Cochran											
Address: 2 Facility Nar		Telephone No.: 505-326-9457 Facility Type: natural gas well API # 30-045-24645											
,													
Surface Ow	ner: Fede	ral	Federal Lease No. NMSF 078905)5				
LOCATION OF RELEASE													
Unit Letter D	Section 13	Township 28N	Range 12W	Feet from the 840	North North	/South Line	Feet from the 1050	East/\ West	West Line	County: 3	San Jua	in	
Latitude_36.66716Longitude108.06842													
NATURE OF RELEASE													
Type of Rele	ase conden	Volume of Release: Volume R				Recovered: none							
Source of Re	lease: stuff	Date and I	Date and Hour of Occurrence: Date and Historical Release			Hour of Discovery: 2/25/2011							
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required							If YES, To Whom?						
By Whom?		Date and Hour:											
Was a Watercourse Reached? ☐ Yes ☑ No						If YES, Volume Impacting the Watercourse. RCUD MAY 6 '11							
If a Watercourse was Impacted, Describe Fully.* OIL CONS. DIV.													
							DIST. 3						
Describe Cause of Problem and Remedial Action Taken.*													
Staining of soil was visible near wellhead. Stuffing box leak was determined as the cause of stained soil. Stained soil was excavated and taken to landfarm to remediate.													
Describe Assa Affected and Cleanum Action Tokan *													
Describe Area Affected and Cleanup Action Taken.* An area near the wellhead and projecting NE of wellhead was excavated. The total amount of soil removed was 6000 cubic feet/220 cubic yards of impacted soil A large stockpile of soil to the east of the wellhead was also tested using 5 point composite and passed standards. This soil was spread thinly on the east side of the location.													
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
OIL CONSERVATION DIVISION													
Signature:													
Printed Name	: Courtney	Cochran		Approved by District Supervisor:									
Title: Environmental Challenger						Approval Dat	pproval Date: 12-1-11 Expiration Date:						
E-mail Address: Courtney.Cochran@bp.com						Conditions of Approval:				Attached			

* Attach Additional Sheets If Necessary

Date: 5/4/2011

Phone: 326-9457

Submit sample results to
NMOCP

NJK1200948624