## **Deviation Report**

	- · · · · · · · · · · · · · · · · · · ·	
Name of Company	Address	
Burlington Resources Oil & Gas Company	P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number (API Number)	Location	Sec. Twn. Rge.
SAN JUAN 28-6 UNIT #117M (30-039-29356)	-1180 FSL -2510 FWL	10-028N-006W
Pool and Formation	County	State
Blanco Mesaverde/Basin Dakota	RIO ARRIBA	NEW MEXICO

(OH)

Depth (ft)	<b>Deviation (degrees)</b>
60	1.00
120	1.00
620	0.50
1,119	1.00
1,620	1.25
2,109	1.75
2,558	1.25
2,859	1.00
3,338	0.75
3,567	0.75
7,715	0.75



nufe In Mc Carthy

Air Hammer Used? YES/NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 1st day of April, 2005.

Notary Public in and for San Juan County, New Mexico

My commission expires September 15, 2008.