District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III

1000 Rio Brazos Road, Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District IV

## State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Revised October 10, 2003

Form C-141

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Release Notification and Corrective Action					
30-045-26902		OP	<b>OPERATOR</b>		Initial Report
Name of Company Burlington Resources, a whol			Contact	Kristina Kovach	
owned subsidiary of ConocoPhillips Company					
Address	3401 E. 30 <sup>th</sup> St., Farmington, NM 87402		Telephone No.	505-326-9866	
Facility Name	Howell D #351		Facility Type	Gas Well	API # 30-045-26902
Surface Owner	Federal	Mineral Owner	Federal		Lease No. <b>SF-078387</b>
				_	

LOCATION OF RELEASE North/South Line Feet from the Feet from the Unit Letter Section Township Range East/West Line County R8W 1180' Ν 29 T31N-South 1840' West San Juan 107.70151 ° W 36.86498° N Longitude Latitude NATURE OF RELEASE Type of Release - Produced Water Volume of Release - 12 BBL Volume Recovered - 10 BBL Source of Release: Tank leak Date and Hour of Occurrence Date and Hour of Discovery unknown 5/30/08 - 5:00 p.m. Was Immediate Notice Given? If YES, To Whom? RCVD JUN 5'08 ☐ Yes ☐ No ☒ Not Required OCD - Brandon Powell via email OIL CONS. DIV. BLM - Kevin Schneider via email Kristina Kovach Date and Hour - 6/4/08 - 4:00 p.m. By Whom? DIST. 3 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse. ☐ Yes ☒ No If a Watercourse was Impacted, Describe Fully.\* Describe Cause of Problem and Remedial Action Taken.\* A Triple S employee discovered a produced water spill of approximately 12 BBL at the Howell D #351 on the afternoon of 5/30/08. The release was caused by a valve on the water tank that was not closed completely. Upon discovery, the employee shut the valve completely. A water truck was called in to remove standing liquid. Describe Area Affected and Cleanup Action Taken.\* All of the spilled fluids were contained within the berm, and approximately 10 BBL of produced water were recovered by vacuum truck. A COPC employee raked the affected area. COPC will continue to monitor soil conditions to determine if further remediation is necessary. To prevent reoccurrence, COPC will talk to water haulers about closing valves completely. I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. OIL CONSERVATION DIVISION Signature: Austina March Approved by District Supervisor\ Kristina L. Kovach Printed Name: **Expiration Date: Environmental Associate** Title: E-mail Address: kristina.l.kovach@conocophillips.com Conditions of Approval: Attached

Phone: 505-326-9866 Date: \* Attach Additional Sheets If Necessary

MTK 1203835285