

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr , Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-28135

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Energen Resources	Contact
Address 2010 Afton	Telephone No. 505-325-6800
Facility Name Federal 29-9-12 #1	Facility Type: Onshore facility

Surface Owner: Federal	Mineral Owner: Federal	Lease No.
------------------------	------------------------	-----------

LOCATION OF RELEASE

Unit Letter L	Section 12	Township 29N	Range 9W	Feet from the 2150	North/South Line South	Feet from the 1100	East/West Line West	County San Juan
------------------	---------------	-----------------	-------------	-----------------------	---------------------------	-----------------------	------------------------	--------------------

Latitude 36.73793 Longitude -107.73527

NATURE OF RELEASE

Type of Release fire	Volume of Release NA	Volume Recovered NA
Source of Release lighting separator	Date and Hour of Occurrence 1/31/2008 1515	Date and Hour of Discovery 1/31/2008 1515
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell	
By Whom? Kellie Skelton	Date and Hour 2/1/2008 0900	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RCVD MAY 1 '08

OIL CONSV. DIV.
DIST. 3

If a Watercourse was Impacted, Describe Fully.*



NA

Describe Cause of Problem and Remedial Action Taken.*

Condensate had accumulated in the fire tube, when employee tried to relight fire tube there was a flash of fire. Fire went out on its own for the most part. Employee proceeded to extinguish the remaining amounts with a shovel and dirt.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kellie Skelton	Approved by District Supervisor: 	
Title: Environmental Safety Coordinator	Approval Date: 2/6/2008 Expiration Date:	
E-mail Address: kskelton@energen.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/6/2008 Phone: 505-324-4152		

* Attach Additional Sheets If Necessary

25K1203850435