



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 7-28-04 Operator CARAT WESTERN DRILLING API #30-0 39-23347
Property Name Crow Mesa Well No. #2 Location: Unit 6 Section 1819 Township 25 Range 7c
Well Status (Shut-In or Producing) Tubing 385 Intermediate Casing 40 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>40</u>	Steady Flow <u>0</u>	
10 minutes		<u>40</u>	Surges <u>none</u>	
15 minutes		<u>40</u>	Down to Nothing <u>yes</u>	
20 minutes		<u>40</u>	Nothing <u>yes</u>	
25 minutes		<u>40</u>	Gas <u>0</u>	
30 minutes		<u>40</u>	Gas & Water <u>0</u>	
			Water <u>0</u>	

If bradenhead flowed water, check all of the descriptions that apply below:


CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

PACKER IN WELL

Dead



By F. D. E.

Witness

Case operator
(Position)