



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emard.state.nm.us/ocd/District III3district.htm](http://emard.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 3/23/05 Operator COULTAS MNG. API # 30-043-20869

Property Name Erin Well No. 4 Location: Unit F Section 33 Township 18N Range 3W

Well Status (Shut-In or Producing) Tubing _____ Intermediate _____ Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>0</u>	Steady Flow	
10 minutes		<u>0</u>	Surges	
15 minutes		<u>0</u>	Down to Nothing	
20 minutes		<u>0</u>	Nothing <u>X</u>	
25 minutes		<u>0</u>	Gas	
30 minutes		<u>0</u>	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS: no fgs in well, well not producing

