



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://enmrd.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 3/22/05 Operator COHAST m n 6 API #30-0 43 20939

Property Name Erin Well No. 9 Location: Unit B Section 33 Township 18N Range 3W

Well Status(Shut-In or Producing) Tubing 0 Intermediate Casing 0 Bradenhead

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>0</u>	Steady Flow	
10 minutes		<u>0</u>	Surges	
15 minutes		<u>0</u>	Down to Nothing	
20 minutes		<u>0</u>	Nothing <u>X</u>	
25 minutes		<u>0</u>	Gas	
30 minutes		<u>0</u>	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

SURFACE CAISING cement up to SURFACE
Well is producing

By Samon Vasquez
RIG OP.
(Position)

Witness

