

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-24914

OPERATOR

☒ Initial Report ☐ Final Report



Name of Company: BP America Production Co.	Contact: Courtney Cochran	
Address: 200 Energy Ct. Farmington, NM 87401	Telephone No.: 505-326-9457	
Facility Name: Day 2E	Facility Type: natural gas well API # 300452491400	
Surface Owner: Federal	Mineral Owner: Federal	Lease No. SF-078414

LOCATION OF RELEASE

Unit Letter I	Section 08	Township 29N	Range 08W	Feet from the 1750	North/South Line South	Feet from the 1000	East/West Line East	County: San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	------------------

Latitude 36.73718 Longitude 107.69233

NATURE OF RELEASE

Type of Release: natural gas	Volume of Release: 62.5 MCF	Volume Recovered: none
Source of Release: 1 inch nipple on compressor discharge	Date and Hour of Occurrence: 12/31/11 5 am until 1/2/12 7 am	Date and Hour of Discovery: 1/2/12
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
RCVD JAN 25 '12 OIL CONS. DIV. DIST. 3		
Describe Cause of Problem and Remedial Action Taken.* Field technician found 1 inch broken nipple on compressor discharge. Compressor shutdown for repairs.		
Describe Area Affected and Cleanup Action Taken.* Compressor was repaired and well up and flowing. No clean-up was possible. Gas dissipated to atmosphere.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Courtney Cochran	Approved by District Supervisor: 	
Title: Environmental Challenger	Approval Date: 2/27/2012 Expiration Date:	
E-mail Address: Courtney.Cochran@bp.com	Conditions of Approval:	
Date: 1/10/2012 Phone: 505-326-9457	Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

nJK 12058 29934