

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-29460

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Kristina Kovach
Address	3401 E. 30 th St., Farmington, NM 87402	Telephone No.	505-326-9866
Facility Name	San Juan 32-8 Unit #253 TS	Facility Type	Gas Well
		API #	30-045-29460
Surface Owner	Private	Mineral Owner	Federal
		Lease No.	SF 080412-A

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	27	T32N	R8W	1824'	North	1757'	East	San Juan

Latitude 36.95696° N Longitude 107.65980° W



NATURE OF RELEASE

Type of Release - Produced Water	Volume of Release - 25 BBL	Volume Recovered - 20 BBL
Source of Release: Truck backed into transfer station	Date and Hour of Occurrence 3/2/08 - 4:45 a.m.	Date and Hour of Discovery 3/2/08 - 4:45 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD - Brandon Powell via phone & email BLM - Kevin Schneider email	
By Whom? Kristina Kovach	Date and Hour - 3/4/08 - 11:00 a.m.	RCUD MAR 10 '08
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV.	
If a Watercourse was Impacted, Describe Fully.* DIST. 3		

Describe Cause of Problem and Remedial Action Taken.* **A contractor backed into the transfer station at the San Juan 32-8 Unit #253 on the morning of 3/2/08, breaking off the corrosion coupon on the discharge end of the pump and causing a 25 BBL produced water spill. The water hauler contacted a ConocoPhillips employee, who removed the damaged coupon and put the transfer station back in service.**

Describe Area Affected and Cleanup Action Taken.* **All of the spilled fluids remained on location, and 20 BBL were recovered by vacuum truck. We will rake the affected area for further remediation. We will install a guard rail around the transfer station along.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kristina L. Kovach	Approved by District Supervisor: 	
Title: Environmental Associate	Approval Date: 2/27/2012	Expiration Date:
E-mail Address kristina.l.kovach@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/4/08 Phone: 505-326-9866		

* Attach Additional Sheets If Necessary

WJK 1205849752