

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-045-31821

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Noble Energy, Inc.	Contact Chris Del Hierro
Address 5802 U.S. Hwy. 64, Farmington, NM 87401	Telephone No. 303.228.4160
Facility Name McClintock #1-S	Facility Type Tank Battery

Surface Owner Federal	Mineral Owner Federal	Lease No. NMSF078463
------------------------------	------------------------------	-----------------------------

LOCATION OF RELEASE

Unit Letter H	Section 34	Township 31N	Range 13W	Feet from the 1735	North/South Line North	Feet from the 805	East/West Line East	County San Juan
-------------------------	----------------------	------------------------	---------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	---------------------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release – Produced water	Volume of Release ~30 bbls	Volume Recovered ~30 bbls
Source of Release Production equipment (water tank)	Date and Hour of Occurrence 3/6/08 1:00 AM	Date and Hour of Discovery 3/6/08 7:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell – NMOCD, District 3	
By Whom? Chris Del Hierro	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

RCVD MAR 21 '08
OIL CONS. DIV.
DIST. 3



Describe Cause of Problem and Remedial Action Taken.*

Pumper failed to verify produced water tank volume after initiating pumping unit. Water tank overfilled releasing approximately 30 bbls of produced water into the lined berm.

Describe Area Affected and Cleanup Action Taken.*

Water was contained within the lined berm. The well was temporarily shut-in. All material was recovered via vacuum truck and disposed of as produced water at a permitted facility.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chris Del Hierro	Approved by District Supervisor: 	
Title: Environmental Coordinator	Approval Date: 2/27/2012 Expiration Date:	
E-mail Address: cdelhierro@nobleenergyinc.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3/13/08 Phone: 303.228.4160		

* Attach Additional Sheets If Necessary

NJK 1205838689