

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-27252

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	ConocoPhillips Company	Contact	Monica D. Johnson
Address	3401 E. 30 th St., Farmington, NM 87402	Telephone No.	505-326-9829
Facility Name	San Juan 30-5 Unit #213A	Facility Type	Gas Well
		API #	30-039-27252
Surface Owner	Federal	Mineral Owner	Federal
		Lease No.	NM SF-080066

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	5	T30N	R5W	980'	South	760'	East	Rio Arriba

Latitude 36.83704° N Longitude 107.37425° W

NATURE OF RELEASE

Type of Release – Produced water	Volume of Release – 150 BBL	Volume Recovered – 150 BBL
Source of Release: Line break due to freeze	Date and Hour of Occurrence 2/13/08	Date and Hour of Discovery 2/13/08 – 1:10 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD–Brandon Powell via phone & email Kevin Schneider – BLM – via phone & email	
By Whom? Monica D. Johnson	Date and Hour – 2/14/08 – 11 a.m.	RCVD FEB 20 '08
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. OIL CONS. DIV.	



If a Watercourse was Impacted, Describe Fully.*

DIST. 3

Describe Cause of Problem and Remedial Action Taken.* **A ConocoPhillips Company MSO (lease operator) discovered a produced water spill of approximately 150 BBL at the San Juan 30-5 Unit #213A on the afternoon of 2/13/08 due to a line break. The heater in the pump house went out causing the hose to freeze and break. Upon discovery, the valve on the tank was closed. All fluids were contained in the berm and recovered by a vacuum truck.**

Describe Area Affected and Cleanup Action Taken.* **All of the spilled fluids were contained in the berm and recovered. No further reclamation is needed. The heater will be checked to ensure it is operating properly, and the line will be replaced.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kristina L. Kovach	Approved by District Supervisor: 	
Title: Environmental Associate	Approval Date: 2/27/2008	Expiration Date:
E-mail Address: Kristina.L.kovach@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 2/14/08	Phone: 505-326-9866	

* Attach Additional Sheets If Necessary

NJK 1206035504