District I 1625 N French Dr , Hobbs, NM 88240 District II 1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr, Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141 Revised October 10, 2003

Release Notification and Corrective Action														
30-045-33706						OPERA	al Report	\boxtimes	Final Report					
Name of Company Noble Energy, Inc.						Contact Tyson Hutton								
Address 1600 Broadway, Suite 2200 Denver, CO 80202						Telephone No. 303.228.4238								
Facility Name Rio Bravo #27-15						Facility Type Production Pit								
Surface Owner BLM Mineral Owner						BLM I				Lease No. NMSF078463A				
	LOCATION OF RELEASE													
Unit Letter					1				West Line County					
0) 27 31N 13W 500 S				1800 E				San Juan					
Latitude <u>36.864</u> Longitude <u>-108.188</u>														
NATURE OF RELEASE														
Type of Release Produced Water											olume Recovered 15BBL			
Source of Release Production Pit											e and Hour of Discovery 15-2010, 9:05am			
Was Immediate Notice Given?						If YES, To Whom?				10, 9:034111				
Yes No x Not Required														
By Whom?							Date and Hour							
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.							
☐ Yes ⊠ No							N/A RCVD OCT 29 '10							
If a Watercourse was Impacted, Describe Fully * N/A							OIL CONS. DIV.							
IN/A										DIST	. 3			
Describe Cau	Describe Cause of Problem and Remedial Action Taken.*													
1					t to ove	erflow								
	Unanticipated volume of water production caused water vault to overflow													
	Describe Area Affected and Cleanup Action Taken.*													
No produced water was released from the lined secondary containment. Produced water was recovered via vacuum truck and properly disposed of. No additional cleanup will be needed.														
	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
				e is true and comp nd/or file certain r										
				ce of a C-141 repo										
				investigate and r										
or the environment In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.														
, reactur, state	, or room in	yo untu or rego	· · · · · · · · · · · · · · · · · · ·	-		1	OIL CON	SERV	ATION	DIVISIO	N			
Signature.														
Signature	.	Ammount by District Supervisors []												
Printed Name	e: Tyson H	utton			Approved by District Supervisor:									
Title: Envir	onmental S	pecialist			Approval Date: 3/06/20/2 Expiration Date									
						, ,								
E-mail Address: thutton@nobleenergyinc.com						Conditions of Approval Attached								
Date 10/2	26/10	Ph	.228.4238											

* Attach Additional Sheets If Necessary

NJK1206649525

1600 Broadway Suite 2200 Denver, co 80202



Tel 303 228 4000 www nobleenergyinc com

October 26, 2010

Mr. Brandon Powell NMOCD District III 1000 Rio Brazos Road Aztec, NM 87410

RE: Rio Bravo 27-15

Produced Water Spill Report NW/SW Sec. 27–T31N – R13W San Juan County, New Mexico

Dear Mr.Powell:

Please see the attached Incident Report for a water release that occurred on October 15, 2010.

Noble Energy would like to claim business confidentiality protection for the information submitted in this letter, the supporting materials attached and all previous and subsequent correspondence related to this matter.

If you require any additional information please contact me at 303.579.9764.

Sincerely,

Tyson Hutton Environmental Specialist

Attachments

NMOCD Form C-141