



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/DistrictIII/3district.htm>

RCVD MAY 8 '12
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-8-12 Operator Devon API #30-0 45-27341
Property Name Middlebrook SW Well No. 1 Location: Unit 32 Township 31 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 1185 Intermediate 1185 Casing -4 Bradenhead 59.7

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min	0		-4		
10 min	0		-4		
15 min	Jumps ↓		-4		
20 min			-4		
25 min			-4		
30 min			-4		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	✓	
Surges		
Down to Nothing		
Nothing		
Gas	✓	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 4.8

INTERMEDIATE 1185

REMARKS:

Had blow for 3.5 lighter blow to light blow at 4.0
to Jumps at 4 min 15 sec. Jumps - 5-10-15-20-25-
was punched just 4 min. Started blowing Jumps at 25 min.

By [Signature]
(Position)

Witness Monica Cullum

E-mail address _____

When gauge put back on at
30 min
Re-test in 6 months