



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-15-12 Operator Duhon/Tes API #30-0 45-06201
Property Name Vavaso Indian Well No. 1 Location: Unit Section 30 Township 27 Range 8
Well Status (Shut-In or Producing) Initial PSI: Tubing 26.5 Intermediate N/A Casing 28.3 Bradenhead 20.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
2 gal 5 min	Flow		30		
4.5 gal 10 min	Flow		30.5		
7 gal 15 min	Flow		31		
9 gal 20 min	Flow		31.2		
12.5 gal 25 min	Flow		31.5		
14 gal 30 min	Flow		31.7		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow	<u>water</u>	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water	<u>✓</u>	
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 20

INTERMEDIATE N/A

REMARKS:

Shut Compressor tubing Started Churning
BH to nothing in 2 seconds when opened.
Started flowing thumb size water at 1 min surges to

By [Signature]

Witness [Signature]

(Position)

E-mail address

RCVD MAY 15 '12
OIL CONS. DIV.
DIST. 3