



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-15-12 Operator Burlington Gas API #30-0 48-23129

Property Name Serran Well No. 3A Location: Unit 24 Section 27 Township 27 Range 9

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 96.5 Intermediate N/A Casing 100.7 Bradenhead 26

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

FLOW CHARACTERISTICS

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		102.2		
4.5 gal 10 min	flow		102.8		
9.5 gal 15 min	flow		103.5		
14.5 20 min	flow		104.2		
19.5 25 min	flow		104.7		
24.5 30 min	flow		105.2		

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 18.9

INTERMEDIATE N/A

REMARKS:

dead at 5 seconds - started flowing
water at 6 minutes black water at 7 minutes
to clear water at 9 min. gas drop 2.95 on TPO2 just 5 gallons

By M. Z. O.

Witness M. Z. O.

(Position)

clear water rest of 30 min.

E-mail address _____

RCVD MAY 15 '12
OIL CONS. DIV.

DIST. 3