



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-30-12 Operator Burlington Res API #30-0 45-13251
Property Name McClanahan Well No. 3 Location: Unit 24 Section 24 Township 28 Range 10
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 34.4 Intermediate ✓ Casing 34.4 Bradenhead 23.6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
1 gal 5 min	0		34.5		
2 gal 10 min	1.9		34.7		
3 gal 15 min	1.9		34.8		
2 gal 20 min	1.9		34.8		
2 gal 25 min	2.0		34.9		
3 gal 30 min	2.0		34.9		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>✓</u>	<u>DIST. 3</u>
Surges	
Down to Nothing	<u>OIL CONS. OIL</u>
Nothing	<u>RCVD MAY 30 '12</u>
Gas	
Gas & Water	
Water <u>✓</u>	<u>✓</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ✓ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 13

INTERMEDIATE ✓

REMARKS:

Galton in 1 min then test of test flowing 1/2 gallon
a minute. Pressure at start dropped to zero in 2 seconds.
3 gallons beyond test

By Brian VanCaster

Witness Monica Cochran

(Position)

E-mail address _____