Form C-144 July 21, 2008

District I

1625 N French Dr , Hobbs, NM 88240

District il

1301 W Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S St Francis Dr , Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office.

For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and

provide a copy to the appropriate NMOCD District Office.

Pit, Closed-Loop System, Below-Grade Tank, or Proposed Alternative Method Permit or Closure Plan Application Type of action. Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method Colosure of a pit, closed-loop system, below-grade tank, or proposed alternative method Modification to an existing permit Closure plan only submitted for an existing permitted or non-permitted pit, closed-loop system, below-grade tank, or proposed alternative method Instructions: Please submit one application (Form C-144) per individual pit, closed-loop system, below-grade tank or alternative request Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances. Operator WILLIAMS PRODUCTION COMPANY, LLC OGRID# 120782 Address PO Box 640 Aztec, NM 87410 Facility or well name: (ROSA-UNIT-#180 API Number 3004529898 OCD Permit Number: Section ____9N __ Township ___31N ___ Range __06W ___ County SAN JUAN Latitude 36.90908000000000 Longitude 107.47108 NAD: 1983 Surface Owner FEDERAL ROUD MAY SOM 9 Pit: Subsection F or G of 19.15 17 11 NMAC OIL COMS. DIV. Temporary: Drilling Workover ☐ Permanent ☐ Emergency ☐ Cavitation ☐ P&A ☐ Lined ☐ Unlined Liner type. Thickness mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other String-Reinforced Closed-loop System: Subsection H of 19.15 17.11 NMAC Type of Operation P&A Drilling a new well Workover or Drilling (Applies to activities which require prior approval of a permit or notice of intent) ☐ Drying Pad ☐ Above Ground Steel Tanks ☐ Haul-off Bins ☐ Other Lined Unlined Liner type: Thickness _____ mil LLDPE HDPE PVC Other _____ Below-grade-tank: Subsection I of 19 15.17 11 NMAC Volume: _____ bbl Type of fluid. PRODUCED WATER Tank Construction material FIBERGLASS TANK w/BANDED 20-mil HDPE SECONDARY LINER Secondary containment with leak detection [Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off ☐ Visible sidewalls and liner ☐ Visible sidewalls only ☐ Other Liner type Thickness _____ mil HDPE PVC Other ____ Alternative Method:

Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate. Please specify	is ,
7. Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other Monthly inspections (If netting or screening is not physically feasible)	
8. Signs: Subsection C of 19.15.17.11 NMAC 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers Signed in compliance with 19.15.3.103 NMAC	
9. Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau consideration of approval. Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	u office for
Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of accumaterial are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the approfice or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drabove-grade tanks associated with a closed-loop system.	ropriate district approval.
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to temporary, emergency, or cavitation pits and below-grade tanks) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	Yes No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent pits) - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	Yes No
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant WMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	Yes No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	Yes No
Within a 100-year floodplain FEMA map	☐ Yes ☐ No

Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are acached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API Number: or Permit Number:
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Previously Approved Design (attach copy of design) API Number:
Previously Approved Operating and Maintenance Plan AP! Number: (Applies only to closed-loop system that use
above ground steel tanks or haul-off bins and propose to implement waste removal for closure)
Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Leak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC
Proposed Closure: 19.15.17.13 NMAC Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indicate, by a check mark in the box, that the documents are attached. ☐ Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC ☐ Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC ☐ Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) ☐ Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC ☐ Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC ☐ Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC

₩ T		
16.		
Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bi Instructions: Please indentify the facility or facilities for the disposal of liquids, drilling fluids and drill cutt		
facilities are required.		
Disposal Facility Name: Disposal Facility Permit No		
Disposal Facility Name: Disposal Facility Permit No		
Will any of the proposed closed-loop system operations and associated activities occur on or in areas that will r Yes (If yes, please provide the information below) No	not be used for future ser	vice and operations?
Required for impacted areas which will not be used for future service and operations. Soil Backfill and Cover Design Specifications based upon the appropriate requirements of Subsection Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15.17.13 NMAC		c
17. Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommenda provided below. Requests regarding changes to certain siting criteria may require administrative approval fit considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consider demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	rom the appropriate dist	rict office or may be
Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	s	☐ Yes ☐ No ☐ NA
Ground water is between 50 and 100 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	s	Yes No
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	s	☐ Yes ☐ No ☐ NA
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakel lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	oed, sinkhole, or playa	Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of in Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	nitial application.	☐ Yes ☐ No
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use fo watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the tim - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed	e of initial application.	Yes No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality.	-	☐ Yes ☐ No
Within 500 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) o	f the proposed site	☐ Yes ☐ No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division		☐ Yes ☐ No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USG Society; Topographic map	SS; NM Geological	Yes No
Within a 100-year floodplain FEMA map		Yes No
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be at by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NM Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19.15.17.13	1AC	n. Please indicate,

8.	
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the closure plan. Please indi	icate
y a check mark in the box, that the documents are attached.	
Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC	
Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC	
Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19.15.17.11 NMAC	
Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.15.17.11 NMAG	C
Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC	
Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC	
Waste Material Sampling Plan - based upon the appropriate requirements of Subsection F of 19.15.17.13 NMAC	
Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standards cannot be achieved)	
Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	
Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19.15.17.13 NMAC	
☐ Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19.15 17.13 NMAC	

Operator Application Certification:
I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief.
Name (Print): Title:
Signature: Date:
e-mail address: Telephone:
20. OCD Approval: ☐ Permit Application (including closure plan) ☑ Closure Plan (only) ☐ OCD Conditions (see attachment)
OCD Representative Signature: Approval Date: 5/30/2
21. Closure Report (required within 60 days of closure completion): Subsection K of 19.15.17.13 NMAC
Instructions: Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed.
Closure Completion Date: 12 5 2009
22.
Closure Method: Waste Excavation and Removal On-Site Closure Method Alternative Closure Method Waste Removal (Closed-loop systems only) If different from approved plan, please explain.
23. Classura Banart Banarding Wests Banard Classura Four Classed loop Systems That Utilize About Crowned Steel Toules on Hout off Pins Only.
Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only: Instructions: Please indentify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed. Use attachment if more than two facilities were utilized.
Disposal Facility Name: Disposal Facility Permit Number:
Disposal Facility Name: Disposal Facility Permit Number:
Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations? Yes (If yes, please demonstrate compliance to the items below) \sum No
Required for impacted areas which will not be used for future service and operations:
Site Reclamation (Photo Documentation)
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique
☐ Site Reclamation (Photo Documentation) ☐ Soil Backfilling and Cover Installation ☐ Re-vegetation Application Rates and Seeding Technique
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique 24. Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division)
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique 24. Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure)
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique 24. Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable)
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique 24. Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure)
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique 24. Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique 24. Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique 24. Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude Longitude NAD: 1927 1983
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude Longitude NAD: 1927 1983
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude Longitude NAD: 1927 1983 1925 1925 1925 1925 1925 1925 1925 1926 1927 1927 1927 1927 1927 1928 1927 1928 1927 1928 1927 1928
Site Reclamation (Photo Documentation) Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Closure Report Attachment Checklist: Instructions: Each of the following items must be attached to the closure report. Please indicate, by a check mark in the box, that the documents are attached. Proof of Closure Notice (surface owner and division) Proof of Deed Notice (required for on-site closure) Plot Plan (for on-site closures and temporary pits) Confirmation Sampling Analytical Results (if applicable) Waste Material Sampling Analytical Results (required for on-site closure) Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude

Williams Production Co., LLC San Juan Basin: New Mexico Assets

Below-Grade Tank Removal Closure Plan

In accordance with Rule 19.15.17.13 NMAC, the following plan describes the general closure requirements of below-grade tanks (BGT) on Williams Production Co, LLC (WPX) locations in the San Juan Basin of New Mexico. This is WPX's standard closure procedure for all BGTs regulated under Rule 19.15.17 NMAC and operated by WPX. For those closures which do not conform to this standard closure plan, a separate well/pit specific closure plan will be developed and utilized.

Closure Conditions and Timing:

Pursuant to 19.15.17.13 (A) NMAC, WPX will initiate closure of any BGT should any one of these conditions occur:

- The Division requires closure because of imminent danger to fresh water, public health or the environment.
- The integrity of the BGT fails. Notification will be within 48 hours to the Division and closure will be schedule as specified in 19.15.17.12 (A)(5) NMAC.
- WPX chooses to take the BGT out-of-service due to operational needs. Closure under these conditions will be closed within 60 days of cessation of the BGT's operation.
- BGTs installed prior to June 16, 2008 that do not meet the requirements under 19.15.17.11.1(6) NMAC and WPX chooses not to retrofit or upgrade. Closure under these conditions will be completed within five years (by June 16, 2013).

General Plan Requirements:

- 1. Prior to initiating any BGT Closure except in the case of an emergency, WPX will review County Tax Records for the current surface owner of record. The surface owner of record will be notified of the intent to closure the BGT by certified mail and a copy of this notification will be included in the closure report. In the case of an emergency, the surface owner of record will be notified as soon as practical.
- Notice of Closure will be given to the Aztec District office between 72 hours and one
 week of the scheduled closure via email or phone. The notification of closure will
 include the following:
 - a. Operators Name (WPX)
 - b. Well Name and API Number
 - c. Location (USTR)
- 3. All piping will be rerouted to an alternative produced water storage/disposal location (e.g. surface tanks, temporary frac tank, ...). The well will be temporarily shutin until the rerouting is completed.
- 4. All produced water will be removed from the BGT following discharge-pipe rerouting. Produced water will be disposed at one of the following NMOCD approved facilities depending on the proximity of the BGT site: Rosa Unit SWD #1 (Order: SWD-916, API: 30-039-27055), Rosa Unit #94 (Order: SWD-3RP-1003-0, API: 30-039-23035), Jillson Fed. SWD #001 (Order: R10168/R10168A, API: 30-039-25465), Middle Mesa SWD #001 (Order: SWD-350-0, API: 30-045-27004) and/or Basin Disposal (Permit: NM-01-0005).
- 5. Solids and sludges will be shoveled and /or vacuumed out for disposal at Envirotech (Permit Number NM-01-0011).
- 6. WPX will obtain prior approval from NMOCD to dispose, recycle, reuse, or reclaim the BGT and provide documentation of the disposition of the BGT in the closure report. Steel materials will be recycled or reused as approved by the Division. Fiberglass tanks will be empty, cut up or shredded, and EPA cleaned for disposal as solid waste. Liners materials will be cleaned without soils or contaminated material for disposal as

- solid waste. Fiber is ass tanks and liner materials will meet the conditions of paragraph 1 subsection D of 19.15.9.712 NMAC. Disposal will be at a licensed disposal facility, presently San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426.
- 7. Any equipment associated with the BGT that is no longer required for some other purpose, following the closure will be removed from the location.
- 8. Following removal of the tank and any liner material, a five-point composite sample will be taken of the excavation and tested per 19.15.17.13(E)(4) NMAC as identified in Table 1. Grab samples will be collected from any area that is wet, discolored or showing other evidence of a release. Results will be report to the Division following receipt from the lab on Form C-141.

Table 1: Closure Criteria for BGTs

Components	Testing Methods	Closure Limits (mg/Kg)
Benzene	EPA SW-846 Method 8021B or 8260B	0.2
BTEX	EPA SW-846 Method 8021B or 8260B	50
TPH	EPA SW-846 Method 418.1(1)	100
Chlorides	EPA SW-846 Method 300.1(1)	250 ⁽²⁾

- (i) Method modified for solid waste.
- $^{(2)}$ If background concentration of Chlorides greater than 250 mg/Kg, then higher concentration will be used for closure.
- 9. If the Division and/or WPX determine there is a release, WPX will comply with 19.15.3.116 NMAC and 19.15.1.19 NMAC.
- 10. Upon completion of the tank removal, the excavation will be backfilled with non-waste earthen material compacted and covered with a minimum of one foot of top soil or background thickness whichever is greater and to existing grade. The surface will be recontoured to match the native grade and prevent ponding.
- 11. For those portions of the former pit area no longer required for production activities, WPX will seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs. Note: If a surface owner agreement requires reseeding or other surface restoration that do not meet the revegetation requirements of 19.15.17.13.1 NMAC then WPX will submit the proposed alternative with written documentation that the surface owner agrees to the alternative, for Division approval.
- 12. For those portions of the former pit area required for production activities, reseeding will be done at well abandonment, and following the procedure noted above.

Closure Report:

All closure activities will include proper documentation and will be submitted to OCD within 60 days of the BGT closure on a Closure Report using Division Form C-144. The Report will include the following:

- Proof of Closure Notice (surface owner & NMOCD)
- Backfilling & Cover Installation
- Site Diagram with coordinates
- Available Inspection reports

- Confirmation Sampling Analytical Results
- Disposal Facility Name(s) and Permit Number(s)
- Application Rate & Seeding techniques
- Photo Documentation of Reclamation



From: Lane, Myke

Sent: Friday, November 20, 2009 9:21 AM

To: Powell, Brandon, EMNRD

Cc: Meador, Tasha; Lucero, Christopher

Subject: Closure Notice - Rosa 180 BGT

Williams has tentatively scheduled the closure of the following BGT next week pending availability of resources and weather conditions.

WELLSITE	API	FMT	SEC	TWN	RNG
Rosa #180	3004529898	BLANCO MV	9 (N)	31N	06W

Please contact me if there are any problems or you request additional information. Thanks for your consideration

Michael K. (Myke) Lane, PE EH&S Team Leader - San Juan Basin Operations 721 S. Main/PO Box 640, Aztec, NM 87410 (505) 634-4219(off); -4205(fax); 330-3198(cell)

"The problems we face cannot be resolved at the same level of thinking as that which gave rise to them!"--- shared with me by Brent Hale



Williams Production Co., LLC San Juan Basin: New Mexico Assets

Below-Grade Tank Removal Closure Report

Well: (Rosa Unit#180)
API No: 30-04529898

Location: N-S09-T31N-R06W, NMPM

In accordance with Rule 19.15.17.13 NMAC, the following report describes the general closure of the referenced below-grade tanks (BGT) on Williams Production Co, LLC (WPX) location in the San Juan Basin of New Mexico. The closure follows this WPX's standard closure procedure for all BGTs regulated under Rule 19.15.17 NMAC and operated by WPX. For those closures which do not conform to the standard closure plan, a separate well/pit specific closure plan will be developed and utilized.

Closure Conditions and Timing:

Pursuant to 19.15.17.13 (A) NMAC, WPX will initiate closure of any BGT should any one of these conditions occur:

- The Division requires closure because of imminent danger to fresh water, public health or the environment.
- The integrity of the BGT fails. Notification will be within 48 hours to the Division and closure will be schedule as specified in 19.15.17.12 (A) (5) NMAC.
- WPX chooses to take the BGT out-of-service due to operational needs. Closure
 under these conditions will be initiated within 60 days of cessation of the BGT's
 operation.
- BGTs installed prior to June 16, 2008 that do not meet the requirements under 19.15.17.11.1(6) NMAC and WPX chooses not to retrofit or upgrade. Closure under these conditions will be completed within five years (by June 16, 2013).

General Plan Requirements:

Prior to initiating any BGT Closure except in the case of an emergency, WPX will
review County Tax Records for the current landowner of record. The landowner of
record will be notified of the intent to closure the BGT by certified mail and a copy of
this notification will be included in the closure report. In the case of an emergency,
the landowner of record will be notified as soon as practical.

<u>Williams notified the SMA of its intent to clean close the BGT via Certified Mail on March 10, 2009 see attached. No return receipt required per BLM:FFO/NMOCD MOU dated 5/4/09.</u>

- 2. Notice of Closure will be given to the Aztec District office between 72 hours and one week of the scheduled closure via email or phone. The notification of closure will include the following:
 - a. Operators Name (WPX)
 - b. Well Name and API Number
 - c. Location (USTR)

Aztec District office was notified of Williams E&P intent to close on (10/16/2009). Email attached.

3. All piping will be rerouted to an alternative produced water storage/disposal location (e.g. surface tanks, temporary frac tank, ...). The well will be temporarily shut-in until the rerouting is completed.

Williams closed the BGT used by the Rosa Unit#180 separator and piped all liquids to the Produced Water Storage Tank.

4. All produced water will be removed from the BGT following discharge-pipe rerouting. Produced water will be disposed at one of the following NMOCD approved facilities depending on the proximity of the BGT site: Rosa Unit SWD #1 (Order: SWD-916, API: 30-039-27055), Rosa Unit #94 (Order: SWD-3RP-1003-0, API: 30-039-23035), Jillson Fed. SWD #001 (Order: R10168/R10168A, API: 30-039-25465), Middle Mesa SWD #001 (Order: SWD-350-0, API: 30-045-27004) and/or Basin Disposal (Permit: NM-01-0005).

5. Solids and sludges will be shoveled and /or vacuumed out for disposal at Envirotech (Permit Number NM-01-0011).

Produced water in the BGT prior to closures was removed by vacuum truck and hauled

No solids or sludge required removal prior to excavation and removal of the tank.

6. Williams will obtain prior approval from NMOCD to dispose, recycle, reuse, or reclaim the BGT and provide documentation of the disposition of the BGT in the closure report. Steel materials will be recycled or reused as approved by the Division. Fiberglass tanks will be empty, cut up or shredded, and EPA cleaned for disposal as solid waste. Liners materials will be cleaned without soils or contaminated material for disposal as solid waste. Fiberglass tanks and liner materials will meet the conditions of paragraph 1 subsection D or 19.15.9.712 NMAC. Disposal will be at a licensed disposal facility, presently San Juan Regional Landfill operated by Waste Management under NMED Permit SWM-052426.

The fiberglass tank and plastic liner was disposed of at the San Juan Regional Landfill.

- 7. Any equipment associated with the BGT that is no longer required for some other purpose, following the closure will be removed from the location.

 The fiberglass tank and plastic liner were removed offsite. All other piping and equipment remains in use. See attached photo.
- 8. Following removal of the tank and any liner material, a five-point composite sample will be taken of the excavation and tested per 19.15.17.13(E)(4) NMAC as identified in Table 1. Grab samples will be collected from any area that is wet, discolored or showing other evidence of a release. Results will be report to the Division following receipt from the lab on Form C-141.

Table 1: Closure Criteria for BGTs

Components	Testing Methods *	Closure Limits (mg/Kg)	Sample Results (mg/Kg)
Benzene	EPA SW-846 Method 8021B or 8260B	ND	ND
BTEX	EPA SW-846 Method 8021B or 8260B	ND	ND
TPH	EPA SW-846 Method 418.1(1)	100	109
Chlorides	EPA SW-846 Method 300.1(1)	250(2)	2

⁽¹⁾ Method modified for solid waste.

to the Rosa Unit disposal wells listed.

9. If the Division and/or Williams determine there is a release, Williams will comply with 19.15.3.116 NMAC and 19.15.1.19 NMAC.

No release detected.

10. Upon completion of the tank removal, and any necessary soil remediation, the excavation will be backfilled with non-waste earthen material compacted to native and covered with a minimum of one foot of top soil or background thickness. The surface will be recontoured to match the native grade.

<u>Pit area backfilled with clean earthen material following sample results. No contaminated soil taken off site.</u> Backfill compacted to avoid settling and pit area remains in use for production operations.

Form C-144 Rosa Unit#180 Oil Conservation Division Page 2 of 3

 $^{^{(2)}}$ If background concentration of Chlorides greater than 250 mg/Kg, then higher concentration will be used for closure.

11. For those portions of the former pit area no longer required for production activities, WPX will seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via drilling on the contour whenever practical, or by other Division-approved methods. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintained that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs. Note: WPX assumes the seeding stipulations including mix and seeding methods specified by the Surface Management Agency (BLM, BOR, USFS, Tribal, etc.) APD are Division-approved methods unless notified by the Division of their unacceptability. If a landowner agreement requires reseeding or other surface restoration that does not meet the revegetation requirements of 19.15.17.13., I then WPX will submit the proposed alternative with written documentation that the landowner agrees to the alternative, for Division approval.

<u>Pit area along with unused portions of well pad interim reclaimed and following P&A entire location to be reclaimed and recontoured in accordance with Surface Management Agency requirements in APD-COAs and per BLM:FFO/NMOCD MOU dated 5/4/09.</u>

12. For those portions of the former pit area required for production activities, reseeding will be done at well abandonment, and following the procedure noted above. See above notes.

Closure Report:

All closure activities will include proper documentation and will be submitted to OCD within 60 days of the BGT closure on a Closure Report using Division Form C-144. The Report will include the following:

- Proof of Closure Notice (surface owner & NMOCD)
- Backfilling & Cover Installation
- Site Diagram with coordinates
- Available Inspection reports

- Confirmation Sampling Analytical Results
- Disposal Facility Name(s) and Permit Number(s)
- Re-vegetation Application Rate & Seeding techniques
- Photo Documentation of Reclamation



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics **Total Petroleum Hydrocarbons**

Client:	WPX	Project #:	04108-0003
Sample ID:	Rosa 180	Date Reported:	12-01-09
Laboratory Number:	52559	Date Sampled:	11-29-09
Chain of Custody No-	8486	Date Received:	11-30-09
Sample Matrix:	Soil	Date Extracted:	11-30-09
Preservative:	Cool	Date Analyzed:	12-01-09
Condition:	Intact	Analysis Requested:	8015 TPH

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	ND	0.2
Diesel Range (C10 - C28)	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

Rosa 180

5796 US Highway 64, Farmington, NM 87401 Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com envirotech-inc.com



EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Quality Assurance Report

Client:	QA/QC	Project #:	N/A
Sample ID:	12-01-09 QA/QC	Date Reported:	12-01-09
Laboratory Number:	52543	Date Sampled:	N/A
Sample Matrix:	Methylene Chloride	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	12-01-09
Condition:	N/A	Analysis Requested:	TPH

	POBJERION	a right Here	COGNER	% other eace	- Accept Renge
Gasoline Range C5 - C10	05-07-07	1.1917E+003	1.1922E+003	0.04%	0 - 15%
Diesel Range C10 - C28	05-07-07	1.2305E+003	1.2310E+003	0.04%	0 - 15%

Blank@one.(mg/le.me/kg)	Congettialion	Delection is in the
Gasoline Range C5 - C10	ND	0.2
Diesel Range C10 - C28	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

Duplicate Conc. (me/Kg).	Simple	Elaplicate	Valentinge.	Accepta Reinge
Gasoline Range C5 - C10	ND	ND	0.0%	0 - 30%
Diesel Range C10 - C28	5.4	5.4	0.0%	0 - 30%

Sinke Companion (A)	semile :	Spikė Atidėd	Spikerkeştil	% Recycly	Accept Range
Gasoline Range C5 - C10	ND	250	252	101%	75 - 125%
Diesel Range C10 - C28	5.4	250	252	98.8%	75 - 125%

ND - Parameter not detected at the stated detection limit.

References:

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996.

Comments:

QA/QC for Samples 52543 - 52545, 52558, 52559, and 52570.

Analyst

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc.com envirotech-inc.com



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	WPX	Project #:	04108-0003
Sample ID:	Rosa 180	Date Reported:	12-01-09
Laboratory Number:	52559	Date Sampled:	11-29-09
Chain of Custody:	8486	Date Received:	11-30-09
Sample Matrix:	Soil	Date Analyzed:	12-01-09
Preservative:	Cool	Date Extracted:	11-30-09
Condition:	Intact	Analysis Requested:	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)
_		
Benzene	ND	0.9
Toluene	ND	1.0
Ethylbenzene	ND	1.0
p,m-Xylene	ND	1.2
o-Xylene	ND	0.9
Total BTEX	ND	

ND - Parameter not detected at the stated detection limit.

Surrogate Recoveries:	Parameter	Percent Recovery		
	Fluorobenzene	96.0 %		
	1,4-difluorobenzene	96.0 %		
	Bromochlorobenzene	96.0 %		

References:

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996.

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996.

Comments:

Rosa 180

Analyst



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client:	N/A	Project #:	N/A
Sample ID:	12-01-BT QA/QC	Date Reported:	12-01-09
Laboratory Number:	52543	Date Sampled:	N/A
Sample Matrix:	Soil	Date Received:	N/A
Preservative:	N/A	Date Analyzed:	12-01-09
Condition:	N/A	Analysis:	BTEX

Salibration and Decration Limits (49/1)	Ligal Rr.	PG-GBIRE Achept Hop	%e m 19 0 - 16%	Goac	Defect: (Emilia
Benzene	1,4680E+006	1,4709E+006	0.2%	ND	0.1
Toluene	1 4145E+006	1.4173E+006	0.2%	ND	0.1
Ethylbenzene	1.3072E+006	1.3098E+006	0.2%	ND	0.1
p,m-Xylene	3.2509E+006	3.2574E+006	0.2%	ND	0.1
o-Xylene	1,3368E+006	1.3395E+006	0.2%	ND	0.1

emplicate compatibility)	assa Siampias sus subj	plicate +	ZADIU	Accept Range	Prodest init
Benzene	ND	NĐ	0.0%	0 - 30%	0.9
Toluene	ND	ND	0.0%	0 - 30%	1.0
Ethylbenzene	ND	ND	0.0%	0 - 30%	1.0
p,m-Xylene	ND	ND	0.0%	0 - 30%	1.2
o-Xylene	ND	ND	0.0%	0 - 30%	0.9

Spike Conc. (ug/kg)	Sample Am	min(Sulked Spi	edSginple .	% Receivery	Accept Range
Benzene	ND	50.0	49.5	99.0%	39 - 150
Toluene	ND	50.0	49.3	98.6%	46 - 148
Ethylbenzene	ND	50.0	51.3	103%	32 - 160
p,m-Xylene	ND	100	102	102%	46 - 148
o-Xylene	ND	50.0	47.9	95.8%	46 - 148

ND - Parameter not detected at the stated detection limit.

References

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996

Comments:

QA/QC for Samples 52543 - 52545, 52556, 52558 - 52560, and 52570.

Analyst

Review



EPA METHOD 418.1 TOTAL PETROLEUM HYDROCARBONS

)

Client:	WPX	Project #:	04108-0003
Sample ID:	Rosa 180	Date Reported:	12-02-09
Laboratory Number:	52559	Date Sampled:	11-29-09
Chain of Custody No:	8486	Date Received:	11-30-09
Sample Matrix:	Soil	Date Extracted:	11-30-09
Preservative:	Cool	Date Analyzed:	11-30-09
Condition:	Intact	Analysis Needed:	TPH-418.1

Parameter	(mg/kg)	(mg/kg)
	Concentration	Limit
		Det.

Total Petroleum Hydrocarbons

109

5.0

ND = Parameter not detected at the stated detection limit.

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments:

Rosa 180.



EPA METHOD 418.1 TOTAL PETROLEUM HYROCARBONS QUALITY ASSURANCE REPORT

Client:	QA/QC	Project #:	N/A
Sample ID:	QA/QC	Date Reported:	12-02-09
Laboratory Number:	11-30-TPH.QA/QC 52556	Date Sampled:	N/A
Sample Matrix:	Freon-113	Date Analyzed:	11-30-09
Preservative:	N/A	Date Extracted:	11-30-09
Condition:	N/A	Analysis Needed:	TPH

Calibration	l-Cal Date	C-Cal Date	l-Cal RF:	Cal RF: %	Difference	Accept. Range
	11-23-09	11-30-09	1.750	1.690	3.4%	+/- 10%

Blank Conc. (mg/Kg)	Concentration	Detection Limit
TPH	ND	5.0

Duplicate Conc. (mg/Kg)	Sample	Duplicate	% Difference	Accept. Range
TPH	237	244	2.9%	+/- 30%

Spike Conc. (mg/Kg)	Sample	Spike Added	Spike Result	% Recovery	Accept Range
TPH	237	2,000	1,950	87.2%	80 - 120%

ND = Parameter not detected at the stated detection limit.

References: Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978.

Comments: QA/QC for Samples 52556 and 52558 - 52559.



Chloride

WPX Client: Project #: 04108-0003 Sample ID: Rosa 180 Date Reported: 12-02-09 52559 Lab ID#: Date Sampled: 11-29-09 Sample Matrix: Soil Date Received: 11-30-09 Preservative: Cool Date Analyzed: 12-01-09 Condition: Intact Chain of Custody: 8486

Parameter Concentration (mg/Kg)

Total Chloride

2

Reference: U.S.E.P.A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983.

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments: Rosa 180.

Analyst

Review

								_															
Client:	/		Project Name / I	Location:									,	ANAL	YSIS	/ PAR	AME	TERS					
WAX	myke	Cane	RJS	9	180																		
Client Address: /			Sampler Name:	: (/ ~~~~)				TPH (Method 8015)	BTEX (Method 8021)	VOC (Method 8260)	S											
Client Phone No.:			Client No.:						B	Ę,	po	etal	ē		¥		=	ш		ļ		<u>0</u>	lact
			04/	08-0	003				eg	Me	Jet	RCRA 8 Metals	Cation / Anion		TCLP with H/P		TPH (418.1)	CHLORIDE				Sample Cool	Sample Intact
Sample No./	Sample	Sample	Lab No.		ample	No./Volume			\ <u>\{\text{\text{E}}\}</u>	X	S	RA BA	<u>Ş</u>		آم	T	H H	2				фш	ď
Identification	Date	Time	Lab No.		/latrix	of Containers	нус, на		TP	BT	8	윤	Ca	泛	2	PAH	P	동				Sa	Sa
Ross 180	11/29/09	10:00	52559	Solid	Sludge Aqueous	1400	1		×	×							入	X				y	X
	, ,			Soil Solid	Sludge Aqueous																	<i>'</i>	
				Soil Solid	Sludge Aqueous																		
				Soil Solid	Sludge Aqueous																		
				Soil Solid	Sludge Aqueous																		
				Soil Solld	Sludge Aqueous																		
				Soll Solid	Sludge Aqueous																		
				Soil Solid	Sludge Aqueous																		
				Soil Solld	Sludge Aqueous																	,	
				Soil Solid	Sludge Aqueous																		
Relinquished by (Sign	ature)		<u></u>		Date	Time	Rec	eive	d by:	(Sign	ature))	<u> </u>	//					·	D	ate	Ti	ime
	عمست				11/30/29	0415	- 7	5	- 	1	2	<u>\</u>			,	_				lik	109	19	15
Relinquished by: (Sign	ature)				13:7		Réc	eive	ed by:	(Sign	ature	1	ee ?							1/2	7-1		.1
Relinquished by: (Sign	ature)						Red	eive	d by:	(Sign	ature))									_		
						<u> </u>														<u></u>			
XXUS	4			4-		env		rc	t	e	C	h											



Analytical Laboratory

5796 US Highway 64 • Farmington, NM 87401 • 505-632-0615 • lab@envirotech-inc.com

District I 1625 N. French Dr., Hobbs, NM 88240 District J.
130; W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141 Revised October 10, 2003

1220 South St. Francis Dr. Santa Fe, NM 87505

			Rele	ease Notific	catio	n and Co	orrective A	ction	1				
						OPERA?	ГOR			al Report		Final Report	
Name of Co				CTION, LLC			Tasha Meador						
Address			40, AZTI	EC, NM 87410		Telephone No. (505) 634-4241							
Facility Nar	ne Rosa U	nit 180				Facility Typ	e Well Site						
Surface Ow	ner BLM			Mineral C)wner				Lease N	No.			
			ATIO	N OF REI	LEASE								
Unit Letter	Section	Township	Range	Feet from the	North	South Line	Feet from the	East/V	Vest Line	County San Juan			
N	09	31 N	06W										
		1	_atitude_	36.909080	I	_ongitude	107.47108_						
				NAT	URE	OF RELI	EASE						
Type of Relea		ease Occured				Volume of				Recovered			
Source of Rel Was Immedia		Siven?				If YES, To	Non?	e]	Date and	Hour of Dis	covery		
was miniedia	ne nonce (Yes [No 🛭 Not Re	equired	11 123, 10	WHOID!						
By Whom?						Date and H							
Was a Water	course Read		Yes 🛭	1 No		If YES, Vo	dume Impacting t	he Wate	ercourse.				
						<u>L</u>							
If a Watercou	rse was Im	pacted, Descri	be Fully.	* N/A									
												,	
Dasoribu Cou	se of Probl	em and Remed	tial Action	n Taken *									
No action req		ciii ailu Keillei	nai Actioi	ii i akcii.									
'													
Describe Are	a Affected	and Cleanup A	Action Tak	en.*	·								
.,,,													
N/A													
				is true and comp									
				nd/or file certain r ce of a C-141 repo									
should their o	perations h	ave failed to a	dequately	investigate and r	emediat	e contaminati	on that pose a thre	eat to gr	ound water	, surface wa	iter, hui	man health	
or the environ	iment. In a	ddition, NMO	CD accep	tance of a C-141	report d	oes not reliev	e the operator of r	responsi	bility for c	ompliance w	ith any	other	
rederal, state,	or local lay	ws and/or regu	lations.				OIL CONS	CEDV	ATION	DIVISIO	NI.		
()		and I	n+ c.		İ		OIL CON.	SLIK V	ATION	DIVISIC	718		
Signature:		VALVIC	4)										
Printed Name	: Tasha M	, leador				Approved by	District Supervise	or:					
				· · · · · · · · · · · · · · · · · · ·		Anne1 D :			Duminot's	Data:			
Title: EH&S	Coordinate	Or				Approval Dat	e:		Expiration	Date:			
	· · · · · ·	meador@willi	ams.com			Conditions of	Approval:			Attached			
Date:	X1110		Phone	(505) 634-4241									

^{*} Attach Additional Sheets If Necessary



Exploration & Principles PO B to 640 Avia (INM 61137 6067634 4719 6067634 4214 to

March 10, 2009

Mr. Mark Kelly Bureau of Land Management Farmington Field Office 1235 La Plata Hwy Farmington, NM 87401

Sent via Certified Mail.

RE Notification of Production Pit Closure
Rule 19 15 17 13 NMAC
Production Pits associated Natural Gas Development

Į

Production Pits associated Natural Gas Developmen Operated by Williams Production Co. LLC

Pursuant to Rule 19 15 17 13 NMAC, this correspondence is to notify the Bureau of Land Management, Farmington Field Office, of Williams Production LLC's (Williams') intent to clean close all production pits on the attached list of wells operated with the District in San Juan County and Rio Arriba County, New Mexico. Closure will follow the plan included with this correspondence.

Thank you for your consideration. If there are any questions or additional information is requested, please contact me at (505) 634-4209.

Respectfully submitted

Holly C #erkins EH&S Specialist

Encl. Williams Production Pit Inventory List (Federal wells)

San Juan Basin New Mexico Assets Below-Grade Tank Closure Plan

cc Environmental Fig.

Williams Production Co., LLC San Juan Basin: New Mexico Assets

Retow Crade Tank Removal Closure Han

requirements of holowignore tooks (BC+1) on Williams Fradoction Co. H.C. (WPX) locations in the San Joan Basin of New Mexico - This is WPX is tandard closure proceeding for all EC+1s regulated under Role 19.15.17 times and operated by WEX. For those closures which do not conform to this standard closure plan a separate well/pit specific closure plan will be developed and utilized.

Closure Conditions and Timing:

1

Poisoont to 19.15.17.13 (A) NMAC - WPX will initiate closure of any EGF should any one of these conditions occur.

- The Division requires closure because of imminient danger to freshwater public health or the environment
- The integrity of the BC-L fails. Notification will be within 48 hours to the Division and closure will be schedule as specified in 19.15.17.12 [A)[5] NMAC.
- VPX chooses to take the BGT out of service doe to operational needs. Closure under these
 conditions will be closed within 60 days of cessation of the BGT's operation.
- BG3s installed prior to Jone 16, 2008 that do not meet the requirements under 19,15.17.11.1(6).
 BMAC and WEX chooses not to retrofit or approach. Closure under these conditions will be completed within five years (by June 16, 2013).

General Plan Requirements:

- Prior to initiating any BGT Closure except in the case of an emergency. WPX will review County Tax Records for the current surface owner of record. The surface owner of record will be notified of the intent to close the EGT by certified mail and a copy of this notification will be included in the closure report. In the case of an emergency, the surface owner of record will be notified as soon as practical.
- 2 Notice of Closure will be given to the Aztec District office between 72 hoors and one week of the scheduled closure via email or phone. The notification of closure will include the following.
 - a Operators Name (WPX)
 - b. Well Name and All Number
 - c Location (USIR)
- All piping will be rerouted to an alternative produced water storage/disposal location (e.g. surface tanks temporary tracitank...). The well will be temporarily shot in until the rerouting is completed.
- 4 All produced water will be removed from the BGT following discharge pipe rerouting Produced water will be disposed at one of the following MMOCD approved facilities depending on the proximity of the BGT site. Rosa Unit SWD #1 (Order SWD 916-AP) 30-039-27055). Rosa Unit #94 (Order: SWD 3RP 1003-0-AP) 30-039-23035), Jillson Fed. SWD #001 (Order: R10168/R10168A-AP); 30-039-25465). Middle Mesa SWD #001 (Order-SWD 350-0-AP), 30-045-27004) and/or Basin Disposal (Permit-NM-01-0005).

solids and studges will be shoveled and vorva, urins a out for disposal at Envirotech (Permit Number NM 01-001)

with valuation photopproval from NMOCD to alspose a cival trease of reciain the BC $^{-1}$ and provide documentation of the disposition of the BC $^{-1}$ in the closure report. Since the provide will be recycled or reuseo as approved by the Division. Obergias, tanks will be ensure that or greated and ELA cleaned for also so so a solio waste. Their materials with

be cleaned without soils or contaminated material for disposal as solid waste. Till, egglys tanks and liner materials will meet the conditions of paragraph 1 sense clien D of 19.17, 9.17 MMAC. Disposal will be at a license defisions of disposal for inty presently Son Joan & gional paragraph operated by Waste Management under MMLD Lemit SWM ob242s.

- Any equipment associated with the BOI that is no longer regular differsome other purpose tollowing the closure will be removed from the torration.
- taken of the excavation and any liner material of five point composite sample will be taken of the excavation and tested per 19.15.17.13(1)(4) NMAC as identified in Table 1. Grab samples will be collected from any area that is well discolored a showing other evidence of a telease. Results will be report to the Division following recept from the lab on Form C. 14)

,		Table 1 Closure Cintena for BGIs	
	Components	Testing Methods	Closure Limits (mg/Kg)
	Benzene	FPA SW 846 Method 8021B of 8260B	0.2
	BTEX	H'A SW-846 Method 8021B of 8260B	50
	11:11	EF'A SW 846 Method 418.119	100
	Chlondes	FPA SW 846 Method 300 101	25 0 00

Method modified for solid waste.

If background can rentration of a monaction-after than 250 map is a calling for concentration where used for decine

- 5 If the Division and/or WPX determine there is a release. WPX will comply with 19.15.3-116. TIMAC and 19.15.1.19 NMAC.
- Upon completion of the tank removal, the excavation will be backfilled with non-waste earther material compacted and covered with a minimum of one foot of top soil or background thickness whichever is greater and to existing groad. The surface will be recontoured to match the native grade and prevent panding.
- for those portions of the former pit area no longer required for production activities. Whi will seed the disturbed areas the first growing season after the pit is covered. Seeding will be accomplished via diffling on the confour whenever practical or by other Division approved methods. Vegetative cover will equal 70% of the notive perennial vegetative cover (un impacted) consisting of at least three native plant species, including at least one grass that not including no abous weeds, and mointained that cover through two successive growing seasons. Repeal seeding or planting will be confined until successful vegetative growth accurs. Note If a surface owner ogreement requires reseeding or other surface restoration that do not meet revegetation requirements of 15-15.17-13 LIMAC then WTX will submit the proposed attemative with written documentation that the surface owner agrees to the attemative for Division approval.
- 12 For those portions of the former pit area required for production activities reseeding will be done at well abandonment, and following the procedure noted above.

Closure Report

All closure activities will include proper abconventation and will be submitted to OCD within 60 days of the FGT closure on a crosure knowing bivision form C. 144. The keport winner are to totowing.

- From the residence for the contract of the contra
- · Back filmia & cover corner.
- Site I major in various strates.
- Available loguet to testing

- · Committee on Some mile made, in February
- · Lastics and all man become promote enter the analysis of
- Aprili oficio kole a seesi pite, i ma e
- · Francisco (and mours of fee sounds)

WELLS WIFEDERAL SURF MG1							CONSTRUCTION MATERIAL
CCX CANYON UNIT #025	API	<u>FM1</u>	3EC	IVVN	RNG	PIT TYPE	CONSTRUCTION MATERIAL FIBERGLASS TANK w/BANDED 20-mil
COM	3004522537	BLANCOP	17(.	3314	11V√	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
COX CANYON UNIT #025	3004522577	BLANCOTIC	90	3218	111/	BGT	HODE SECONDARY LINER
COX. CANYON DINIT #200	3004527878	BASINTIC	91	3214	111/	BGT	FIBERGLASS TANK WBANDED 20 mil HDPE SECONDARY LINER
COX CANYON UNIT #200A	3004532126	BASINTIL	90	32N	1177	BG1	FIBERGLASS TANK WIBANDED 20 mil HDPE SECONDARY LINER
COX CANYON UNIT #203	3004527872	BASINTIC	17A	32N	1 1 Vv	BG1	LIBERGLASS TANK WBANDED 20-mil HDPE SECONDARY LINER
MADDOX #001	3004511487	BLANCO MV	1010	32N	1 1 Vv	BGT	DBL WALL STEEL
MADDOX #001A	3004523539	BLANCO MV	10F	32N	1177	BG1	DBI WALL STEEL
NM 32-11-#001	3004511309	BLANCO MV	200	32N	111/1	8G1	DBI WALL STEEL
NM 32 11 #001B COM		BASIN DK / BLANCO MV					•
	3004532024	BASIN DK /	203	3214	11W		DBI WALL STEEL
NM 32-11 #001C COM	3004532804	BLANCO MV	201	3214	1 1 VV	BG1	DBL WALL STEET FIBERGLASS TANK W/BANDED 20 mil
NM 32-11 #002 GOM	3004511380	BLANCO MV	194	3214	1111	BGT	HOPE SECONDARY LINER
NM 32-11 #002A COM	3004529017	BLANCO MV	190	32N	1.1Vv	BGT	DBI WALL STEFT
NM 32-11 #002E COM	3004532670	BLANCO MV	191	32N	11Vr	HGT	DBI WALL STEEL
NM 32-11 #002C COM	3004533077	BLANCO MV	19G	32N	1 1 VV	BG1	DBI WALL STEEL
ROSA UNIT #001 SWD	3003927055	SW()	231	31N	06W		DBI WALL STEEL
ROSA UNIT #001E	3003925411	BASIN DK / BLANCO MV	111	3110	0677		FIBERGLASS TANK WEANDED 20 mil HDPE SECONDARY LINER
ROSA UNIT #005A	3003925407	BLANCO MV / ROSA PC	2612	31N	06Vv	BGT	DBI WALL STEFT
ROSA UNIT #005E	3003926927	BASIN DK / BLANCO MV	26B	3111	06W		DBL WALL STEEL
ROSA UNIT #005Y	3003926078	BLANCO MV	2611	31N	06W		FIBERGLASS TANK WBANDED 20 mil- HDPE SECONDARY LINER
ROSA UNIT #008	3003907944	BLANCO MV / ROSA PC	26M	31N	OGVV	BG1	FIBERGLASS TANK W/BANDED 20-mil HDPE SECONDARY LINER
KOSA UNIT #008	3003907944	BLANCO MV / ROSA PC	26M	31N	0677	BG1	FIBERGLASS TANK w/BANDED 20 mil- HDPE SECONDARY LINER
ROSA UNIT #006A	3003925430	BLANCO MV / ROSA PC	26D	31N	06₩	BG1	FIBERGLASS TANK WBANDED 20-mil HDPE SECONDARY LINER
:OSA UNIT #008C	3003926944	BLANCO MV	26N	31N	OGW		FIBERGLASS TANK WBANDED 20-mil HDPE SECONDARY LINER
OSA UNIT #009							FIBERGLASS TANK W/BANDED 20-mil
	3003907975	BLANCO MV BASIN DK /	11K	31N	06W		HDPE SECONDARY LINER
AROON TINU ARO	3003925584	BI ANCO MV	11C	31N	06\^	BGI	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
BROOM TINU ASC	3003927042	BI ANCO MV	11E	3111	OGVV		HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
DSA UNIT #010B	3003926556	BLANCO MV	1311	31N	0674		HDPE SECONDARY LINER
ISA UNIT #010C	3003926918	BLANCO MV	1314	31N	06W	BG7	DBL WALL STEEL
OSA UNIT #UTOC	3003926556	BI ANCO MV	13N	31N	06Vv	BG1	DBI. WALL STEEL

)

WELLS WIFEDERAL							1 ,
SURF MG1	API.	BLANCO MV	SEC	1WN	RNG	PIT TYPE	CONSTRUCTION MATERIAL
ROSA UNIT #012A	3003925900	ROSA PC PASIN DK /	115.1	3111	(WW)	[:(:]	DBI WALL STEEL TIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #012B	3003926555	BLANCO MV	1512	3111	GGVV	EGI	HIDEE SECONDARY LINER
ROSA UNIT #0120	3003929486	BLANCO MV	15çA	4114	(n·W	··(-1	SINGLE WALL STEEL FIBERGLASS TANK WBANDED 20 and
ROSA UNIT #01:	3003907936	BLANCO MV	316	3114	OSVV	BGT	HDPE SECONDARY LINER TIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #013A	3003926298	BLANCO MV BASIN DK /	311	3111	0517	1461	HOPE SECONDARY LINER
ROSA UNIT #013B COM	3003929834	BLANCO MV	31A	31N	05 Vv	EGT	DEL WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #014	3003907958	BI ANCO MV	23B	3111	06W	861	HDPF SECONDARY LINER HBERGLASS TANK WBANDED 20 mil
ROSA UNIT #014A	3003926280	BLANCO MV BASIN DK /	23P	3111	υκίνν	8G)	HILPE SECONDARY LINER
ROSA UNIT #014C	3003930132	BLANCO MV	2311	31N	06Vv	BG1	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #015	3003907946	BLANCO MV	2914	31N	05V¢	BGT	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #016	3003907963	BLANCO MV	1414	3119	ObVv	BGI	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mill
ROSA UNIT #016A	3003925496	BLANCO MV	14(,	31 N	0644	BGI	HDDE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mile
ROSA UNIT #0166	3003926218	BLANCO MV	1414	3118	DGVv	861	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #U17A	3003926272	BLANCO MV BASIN DK /	200	31N	USVV	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #017B	3003926971	BLANCO MV	200	31N	05/7	BG1	HDPE SECONDARY LINER HBERGLASS TANK WBANDED 20 mile
ROSA UNIT #018	3003907960	BLANCO MV ROSA PC BLANCO MV /	22H	31N	06W	HG1	HDPE SECONDARY LINER
ROSA UNIT #016/-	3003925436	ROSA PC	22P	3111	06W	SGI	DBI WALL STEEL
ROSA UNIT #018B	3003927052	BLANCO MV	220	31N	0644	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #019	3003907955	BLANCO MV	24K	3111	GOVV	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #019B	3003926560	BLANCO MV	241	31N	OGW	BG1	HDPE SECONDARY LINER
ROSA UNIT #019C	3003929625	BLANCO MV	24D	31N	OCVV	BGT	DBI WALL STEEL
ROSA UNIT #019C	3003929625	BLANCO MV	24D	3111	OGVV	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #020	3003907969	BLANCO MV	146	31N	OGW	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #020A	3003925495	BLANCO MV	14()	31N	06W	BG1	HDPE SECONDARY LINER
ROSA UNIT #020B	3003926220	BI ANCO MV	14A	31N	06W		DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #020C	3003926221	BLANCO MV	14.J	31N	06VV	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #021A	3003926121	BLANCO MV	23C	31N	OGW	BG1	HDPE SECONDARY LINER
ROSA UNIT #021B	3003926554	BI ANCO MV	23K	31IV	06W		DBI. WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #02!	3003907971	BLANCO MV	18A	3111	05VV		HDPE SECONDARY LINER

WELLS WIFEDERAL SURF MG1	API	FMT	SEC	TWN	RNG	РП ТҮРЕ	
}							FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #022A	3003926390	BLANCO MV	180.	4111	05W	H(3)	HIDDE SECONDARY LINER
							TIBLERGLASS TANK W/BANDED 20 mil
ROSA UIBI #025	3003907947	BLANCO MV	2910	3114	05 <i>V</i> 7	H(!)	HDPE SECONDARY LINER
							TIBERGLASS TANK WIBANDED 20-mit
ROSA UNIT #023E	3003926553	BLANCO MV	291	4114	051/4	861	HDPE SECONDARY LINER
		BASIN DK					FIBERGLASS TANK w/BANDED 20 mil
RÓSA UNIT #023C	3003927609	BLANCO MV	291	3110	0574	BGT	HDPF SECONDARY LINER
							FIBERGLASS TANK w/BANDLD 20-mil
ROSA UNIT #024	3003907933	BLANCO MV	3214	31N	05Vv	BGT	HDPF SECONDARY LINER
		BASIN DK /					
ROSA UNIT #024A	3003925568	BLANCO M√	321	31N	05W	SGT	DBI WALL STEEL
		BASIN DK /					FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #024B	3003926630	BLANCO MV	3214	31N	05VV	BGT	HDPE SECONDARY LINER
		BASIN DK /					FIBERGLASS TANK w/BANDED 20 mit
ROSA UNIT #024C	3003926968	BLANCO MV	32C	31N	05Vv	BGI	HDPE SECONDARY LINER
		BASIN DK /					
ROSA UNIT #026A	3003925580	BI ANCO MV	32O	31N	05W	S(4)	DBI WALL STEEL
12/25/11/11/12/20		DAGUAL (1)				25	24.6
ROSA UNIT #026B	3003926788	BASIN DK	32G	31N	05 V V		DBI WALL STEEL
DC-C & LIBIT 4000	5444.45.4	En chicken this	0.611	5. C. A .	4.0144		FIBERGLASS TANK WBANDED 20 mill
ROSA UNIT #029	3004511136	BLANCO MV	32H	3211	0674		HDPF SECONDARY LINER
ROSA UNIT #029B	20046 20200	BASIN DK /	4.515	6611	0.11		FIBERGLASS TANK WBANDED 20 mil
ILOSA OMIL MOZBE	3004530709	BLANCO MV BASIN DK /	328	3214	ObVV	BGT	HDPE SECONDARY LINER
 ROSA UNIT #029M	3004529584	BLANCO MV	321	3214	OSVV	BGT	DBL WALL STEEL
	POGESCIPING.	BASIN DK /	32)	SZIN	OOVV		FIBERGLASS TANK W/BANDED 20-mil
] [ROSA UNIT #030 C.OM	3003925570	BLANCO MV	120	31N	OGVV		HOPE SECONDARY LINER
TOO SA CHAT HO M CHORD	2002283010	DE MACIO MA	120	3118	OOV		FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #030A	3003926068	BLANCO MV	1214	3114	OGVV		HOPE SECONDARY LINER
Troops of the world	2000980000	ER MICCORIO	1711;	23 13 8	(1(1))		LIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #030B	3003926601	BLANCO MV	12N	31N	GGW		HDPE SECONDARY LINER
				Ç/ 1.14			
ROSA UNIT #030C	3003929842	BLANCO MV	12P	31N	OGVV	BG1	DBI WALL STEEL
							LIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #031	3003926279	BLANCO MV	170	31N	05VV	BG1	HDPE SECONDARY LINER
							FIBERGLASS TANK w/BANDED 20 mit
ROSA UNIT #031A	3003926346	BLANCO MV	171	31N	0EW	BG1	HDPE SECONDARY LINER
		BASIN DK /					FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #031E	3003926579	BLANCO MV	17()	31N	05W	BG1	HDPE SECONDARY LINER
							FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #031C	3003926578	BLANCO MV	17N	3111	05W	BG1	HDPE SECONDARY LINER
		BLANCO MV /					
'ROSA UNIT #032	3003925389	ROSA PC	2111	3111	OGVV	BG1	DBL WALL STEEL
		BLANCO MV /					
ROSA UNIT #0324	3003925417	ROSA PC	211	31N	OOVV		DBI WALL STEEL
12/10/4 1/4/17 2/2/005		BASIN DK /	4.0				FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #032B	3003926771	BLANCO MV	21G	3111	06\%		HDPE SECONDARY LINER
SOCON THAIR WOODS	50.00.00.00	BASIN DK /		0			FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #032C	3003927240	BLANCO MV	216	31N	OGVV		HDPE SECONDARY LINER
DOSA HARIT ANSA	5000003004	OLANCO MA	26.62	2011	Genta		FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #034	3003907984	BLANCO MV	36B	3214	06W	BG1	HDPE SECONDARY LINER
ROSA UNIT #034A	3003926119	BLANCO MV	361	32N	06W	BG1	DBI WALL STEEL
WON CHALL HUME	2002820118	DI ARCO WIY	,1011	32 IV	COVV	001	DOL WALL STEEL
ROSA UNIT #034A	3003926119	BLANCO MV	361	32N	OGW	SGI	DBL WALL STEEL
	SOUDE OF TO	Acres to the Age of the	47771	, •			FIBERGLASS TANK W/BANDED 20-mil
:OSA UNIT #034E	3003926629	BLANCO MV	363	32N	06W		HDPE SECONDARY LINER

)

)

WELLS WIFEDERAL SURF MG1	API	FM1	SEC			PIT TYPE	
ROSA UNIT #0340	3003926969	PLANCO MV	36)3	かい	DGVv	EGI	TIBERGLASS TANK WBANDED 20 mil HDPE SECONDARY LINER
ROSA UNIT #035X	3004510996	ELANCO MV	5k	1111	Oav	BGT	DBE WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #036	3003907977	BLANCO MV	1 1 1 1	3113	(it:ly	R(5)	HDPE SECONDARY LINER LIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #036C	3003930482	BLANCO MV	116	3111	GGVV	£3(51	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #041	3003907981	BLANCO MV BASIN DK /	5K	3117	05W	661	HDPE SECONDARY LINER TIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #041B	3003927014	BLANCO MV	6F ²	31N	051/4	BGT	HDPE SECONDARY LINER
ROSA UNIT #044	3003925873	BLANCO MV	35K	32N	06W	BG1	DBI WALL STEEL
ROSA UNIT #044A	3003926161	BLANCO MV	35E	32N	06Vv	SG1	SINGLE WALL STEEL
ROSA UNIT #044A	3003926161	BLANCO MV	35E	3211	OGVV	SGI	DBI WALL STEEL TIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #044B	3003926685	BLANCO MV	35C	32N	06 V V	BG1	HDPE SECONDARY LINER LIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #045	3003923013	BLANCO MV BASIN DK /	MB	31N	Way	BGT	HDPE SECONDARY LINER LIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #046A	3003926986	BLANCO MV	80	31N	05W	BGT	HDPE SECONDARY LINER
ROSA UNIT #051	3003920289	BASIN DK	23C	31N	06VV	BG1	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #053	3003920293	BASIN DK	88	31N	05Vv	BG1	HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #055	3003920923	BASIN DK	341	31N	wew	BG1	HDPE SECONDARY LINER
ROSA UNIT #059 DK	3003923270	BASIN DK	2514	31N	06W	BG1	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #059 GL	3003923270	UNDES GI	25N	3114	ogyv	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #060	3004529798	BLANCO MV	41	31N	OGVv	BGT	HDPE SECONDARY LINER
ROSA UNIT #064	3003921703	BASIN DK	29A	31N	05₩	BG1	DBI WALL STEEL
ROSA UNIT #064	3003921703	BASIN DK /	29A	31N	06/04	SGI	DBI WALL STEEL
RÓSA UNIT #064M	3003925563	BI ANCO MV	291	3111	05W	BG1	DBI WALL STEEL FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #065	3003921702	BASIN DK	17A	31N	05W	BGT	HOPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #066	3003921758	BASIN DK BASIN DK /	131	31N	06W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #066M	3003925747	BI ANCO MV	13F	31N	06W	BGT	HOPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #072	3003925509	BLANCO MV	Gf	31N	05W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #072A	3003925795	BLANCO MV	6K	31N	VVetO	861	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #075	3004529895	BLANCO MV	101	31N	OGVV	BG1	HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #075A	3004529854	BLANCO MV DK/UNDES	4()	31N	06VV	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #07 ²	3003922538	GL/BLANCO	33L	31N	05W	BG1	HDPE SECONDARY LINER

}

WELLS W/FEDERAL							CONCEDED TO LATERIA
SURF MG1	API	FMT BASIN DK /	SEC	TWN	RNG	PIT TYPE	CONSTRUCTION MATERIAL
ROSA UNIT #079	3003922539	BLANCO MV BASIN DK	22K	3114	0644	EGI	DBI WALL SIFEL
ROSA UNIT #079	3003922539	BLANCO MV BLANCO MV /	22h	3118	06W	SGI	DBI WALL SIFFI
ROSA UNIT #079A	3003925412	ROSA PC BASIN DK /	22{	3113	udW	BGT	DBL WALL STEEL
ROSA UNIT #079E	3003926920	BLANCO MV	22C	3110	DGVV	BGT	DBI WALL STEFF
ROSA UNIT #0790	3003929902	BLANCO MV BASIN DK /	સાર	3114	0544	BGT	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 mile
ROSA UNIT #680	3003922537	BLANCO MV	ВK	31N	05Vv	BG1	HDPE SECONDARY LINER LIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #080A	3003926413	BLANCO MV	ઇ	31N	05W	BGT	HOPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #085	3003922778	BASIN DK	20A	31N	WeW	BG1	HDPE SECONDARY LINER LIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #085	3003922778	BLANCO MV	20A	31N	05W	BG1	HDPE SECONDARY LINER LIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #085A	3003926314	BLANCO MV	20C	31N	05W	BG1	HDPE SECONDARY LINER
ROSA UNIT #085F	3003930130	BLANCO MV	200	3111	05W	BG1	DBI WALL STEEL
ROSA UNIT #086	3003922766	UNDES GL BLANCO MV /	12W	31N	04W	SGT	SINGLE WALL STEEL
ROSA UNIT #086	3004525140	ROSA PC	86:	31N	V/80	BGT	DBI WALL STEEL FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #089	3003922782	BLANCO MV	34A	32N	0677	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #089A	3003925512	BLANCO MV	34O	32N	06W	861	HDPE SECONDARY LINER
ROSA UNIT #089B	3003926851	BLANCO MV	341	32N	06W	BGT	DBI WALL STEEL
ROSA UNIT #089C	3003926674	BLANCO MV	34G	32N	06W	SG1	SINGLE WALL STEFF FIBERGLASS TANK WBANDED 20-mit
ROSA UNIT #090 COM	3004525370	BLANCO MV	33G	32N	0617	BGT	HDPE SECONDARY LINER
ROSA UNIT #090A COM	3004529259	BLANCO MV	33G	3211	06 V V	BG1	DBL WALL STEEL FIBERGLASS TANK WBANDED 20 and
ROSA UNIT #091	3003922780	BLANCO MV	3511	32N	William	BG1	HDPE SECONDARY LINER
ROSA UNIT #091A	3003925790	BLANCO MV -	35O	32N	OBVV	SG1	DBL WALL STEEL
8180# FINU AZOS	3003926684	BI ANCO MV	35P	32N	0644	BGT	DBL WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #091C	3003926991	BLANCO MV	35G	32N	06W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
OSA UNIT #098	3003923265	BASIN DK / GL BASIN DK /	231	3110	0674	BGI	HOPE SECONDARY LINER
OSA UNIT #100B	3003929547	BI ANCO MV	210	31N	OGW	BG1	OBL WALL STEEL
OSA UNIT#100C	3003929851	BLANCO MV BLANCO MV /	21K	31N	06W	BG1	DBI WALL STEEL
DSA UNIT #100E	3003925135	ROSA PC	211	31N	06W	SG1	SINGLE WALL STEEL
DSA UNIT #101M	3003925577	BLANCO MV	24F	3111	06W	BGT	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
)SA UNIT #100	3003923506	BASIN DK / GL	7G	3111	05W	BG1	HDPE SECONDARY LINER

.

WELLS W/FEDERAL				***			
SURF MGT	API	FM1	SEC	TWN	RNG	PIT TYPE	CONSTRUCTION MATERIAL
COX CANYON UNIT #001	3004511397	BLANCO MV	1674	32N	11\%	EG1	DBL WALL STEEL TIBERGLASS TANK W/BANDED 20 mil
COX CANYON UNH #0016	3004522086	BLANCO MV	160.	3214	W	BG1	HDPE SECONDARY LINER LIBERGLASS TANK WBANDED 20 mil
COX CANYON UNIT #001B	3004530791	BLANCO MV	161	32N	11Vv	BG1	HDPF SECONDARY LINER
COX CANYON UNIT #0010	3004532023	BLANCO MV	161-	3210	1 1 VV	BG)	DBL WALL STEEL LIBERGLASS TANK WBANDED 20-mil
COX CANYON UNIT #003	3004511495	BLANCO MV	91	3214	11VV	BGT	HDFL SECONDARY LINER
COX CANYON UNIT #003A	3004522088	BLANCO MV	(45	32N	11 V V	BG1	DBI WALL SHELL
COX CANYON UNIT #003B	3004530871	BLANCO MV	(4.)	32N	1 1 Vv	BG1	DBI WALL STEEL
COX CANYON UNIT #004	3004511368	BLANCO MV	21A	32N	11W	EG1	DBI WALL STEEL
COX CANYON UNIT #004A	3004522093	BLANCO MV	21P	32N	11W	BG1	DEL WALL STEEL
COX CANYON UNIT #004B	3004532186	BLANCO MV	211	32N	11W	BGT	DBI WALL STEEL
COX CANYON UNIT #005	3004511326	BLANCO MV	21K	3214	11V	HGI	DBI WALL STEEL
COX CANYON UNIT #005A	3004522094	BLANCO MV BASIN DK /	21[]	32N	11W	BGT	DBI WALL STEEL
COX CANYON UNIT #0056	3004532142	BLANCO MV	2111	32N	11VV	HGT	DBI WALL STEEL
COX CANYON UNIT #005C	3004533493	BLANCO MV	218	32N	11W	BGI	DBL WALL STEEL
COX CANYON UNIT #006	3004511463	BLANCO MV	16A	32N	1117	BG1	DBL WALL STEEL
COX CANYON UNIT #006A	3004522095	BLANCO MV	161	3214	11W	BGT	DBI WALL SHEL
COX CANYON UNIT #006E	3004532693	BLANCO MV	16B	32N	11Vv	HG1	DBL WALL STEEL
COX CANYON UNIT #006C	3004532733	BLANCO MV	160	32N	11W	BG1	DBI WALL STEEL
COX CANYON UNIT #007	3004511455	BLANCO MV	176	32N	11W	EGP	DBI WALL STEEL
COX CANYON UNIT #007A	3004522091	BLANCO MV	170	32N	11W	BG1	DBI WALL STEEL
COX CANYON UNIT #007C	3004533018	BASIN DK	17K	3211	1 1 VV	BG)	DBL WALL STEEL FIBERGLASS TANK W/BANDED 20 mil
COX CANYON UNIT #008	3004511492	BLANCO MV	81	32N	11W	BG1	HDPE SECONDARY LINER
COX CANYON UNIT #008A	3004522096	BLANCO MV	1714	32N	11 V V	BGT	DBL WALL STEEL FIBERGLASS TANK WBANDED 20-mil
COX CANYON UNIT #008B	3004532080	BLANCO MV	98	32N	11W		HDPE SECONDARY LINER
COX CANYON UNIT #008C	3004531187	BLANCO MV	17P	3211	11W	BGT	FIBERGLASS TANK WBANDED 20 mil HDPE SECONDARY LINER
COX CANYON UNIT #009A COM	3004522092	BLANCO MV	20D	32N	11W		FIBERGLASS TANK W/BANDED 20 mil HDPE SECONDARY LINER
COX CANYON UNIT #009B COM	3004533926	BASIN DK / BLANCO MV	20B	32N	11 V V	BG1	DBI WALL STEEL
COX CANYON UNIT #009C	3003933851	BASIN DK / BLANCO MV	20F	3211	11W		DBI WALI STEEL
COX CANYON UNH #013	3004521489	BLANCO PC	20A	32N	11W		FIBERGLASS TANK w/BANDED 20-mil HDPE SECONDARY LINER

}

3 ' ·

WEILS W/FEDERAL SURF MG1	API	FM1		TWN			CONSTRUCTION MATERIAL
ROSA UNIT #119	3003925143	EASIN DK	1811	3114	05\\		DBL WALL STEEL IBERGLASS JANK WBANDED ZO mil
ROSA UNIT #125	3003925144	PLANCO MW	13B	31N	0644		IDPE SECONDARY LINER
ROSA UMIT #1250	3003929843	BLANCO M\ BASIN DK	13C	2114	OGVv		JBT WALL STEEL IBERGLASS JANK W/BANDED 20 mil
ROSA UNIT #125F	3003925526	BLANCO MV	13.)	3111	OGVv		BOPE SECONDARY LINER
ROSA UNIT #129	3003926304	BLANCO MV	341	32N	0674	BG1 I	OBL WALL STEEL
ROSA UNIT #129A	3003926297	BLANCO MV	34K	3214	OGVV		DBL WALL STEEL IBERGLASS TANK WBANDED 20 mit
ROSA UNIT #137	3003925410	BLANCO MV /	31K	31N	05W		IDPE SECONDARY LINER
ROSA UNIT #137A	3003926129	ROSA PC	311	31N	0517		DBL WALL STEEL IBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #137B	3003927002	BLANCO MV BLANCO MV	31P	31N	05VV	BG1 I	IDPE SECONDARY LINER IBERGLASS LANK WBANDED 20 mil
ROSA UNIT #138	3004529147	ROSA PC BLANCO MV /	17(31N	OGVV		IDPE SECONDARY LINER
ROSA UNIT #138A	3004529134	ROSA PC	1711	3114	OGW	BG1 f	DBI WALL STEEL
ROSA UNIT #138B	3004532168	BLANCO MV	1711	3114	06W	BG1 I	DBI WALL STEFF
ROSA UNIT #139A	3004529600	BLANCO MV	1714	31N	W50	BG1 (DBL WALL STEEL
ROSA UNIT #140	3003925435	ROSA FC	22K	31N	06W	BG1 f	BI WALL STEEL
ROSA UNIT #144	3003925421	ROSA PC	26A	31N	06W	BG1 L	DBI WALL STEEL
ROSA UNIT #145C	3004533086	BLANCO MV	16F	31N	06W		DBL WALL STEEL IBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #146A	3003925513	BLANCO MV	28N	31N	05W		IDPE SECONDARY LINER
ROSA UNIT #146C	3003930187	BLANCO MV	28B	3111	05W	PG) L	OBI WALL STEEL
ROSA UNIT #148	3003925493	BASIN DK	20	31N	ogvv	BG1 1	BI WALL STEEL
ROSA UNIT #148A	3003925776	BLANCO MV	211	31N	06W		DBL WALL STEEL IBERGLASS TANK WIBANDED 20-mil
ROSA UNIT #148B	3003926985	BLANCO MV	2P	31N	0674	BG1 F	IDPE SECONDARY LINER IBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #149	3003925501	BLANCO MV	12G	3117	OGVV		IDPE SECONDARY LINER
ROSA UNIT #149A	3003925807	BLANCO MV BASIN DK /	12F	31fV	OGVV		DBL WALL STEEL TBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #149B	3003926599	BLANCO MV	12E	31N	06W	BG1 F	IDPE SECONDARY LINER IBERGLASS LANK W/BANDED 20-mil
30SA UNIT #150	3004529229	BLANCO MV	32F	32N	06//		IDPE SECONDARY LINER
ROSA UNIT #150A	3004529592	BLANCO MV BASIN DK /	32M	32N	0674	HG1 [DBI WALL STEEL
ROSA UNIT #150B	3004530874	BI ANCO MV	32D	3214	0644	BG1 (OBI WALL STEEL
OSA UNIT #1500	3004532157	BI ANCO MV	32K	32N	W00	BG1 1	OBI WALL STEEL
OSA UNIT #15	3004529267	BLANCO MV	33C	32N	OGVV	BG1 L	BL WALL STEEL

} .

WELLS WIFEDERAL SURF MG1	<u>API</u>	FMT					E CONSTRUCTION MATERIAL
ROSA UNIT #151A	3004529631	BLANCO MV	331	3211	OGVv	b(3)	DBE WALL STEEL
ROSA UNIT #1510.	3004532196	BLANCO MV	3319	32N	OBVv	BG)	DEL WALL STELL LIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #152	.3003925494	BLANCO MV	361	3214	OGW	15651	HOPE SECONDARY LINER
ROSA UNIT #152A	3003925695	BLANCO MV	36N	3514	OGW	BGT	DBL WALL STEEL
ROSA UNIT #152B	3003926631	BLANCO MV	36C	32N	OGVV	BG1	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 nat
ROSA UNIT #152C	3003927635	BLANCO MV	36t	32N	06VV	FGI	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #153	3003925524	BLANCO MV	17()	31N	05VV	BG)	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #153A	3003926329	BLANCO MV BASIN DK /	17A	3110	05Vv	BGT	HDPE SECONDARY LINER LIBERGLASS LANK W/BANDED 20-mil
ROSA UNIT #153B	3003927603	BLANCO MV	171	31N	05W	BGT	HDPE SECONDARY LINER
ROSA UNIT #154	3003925893	BLANCO MV	7N	31N	05W	BGT	DBL WALL STEFT FIBERGLASS TANK w/BANDED 20 mit
ROSA UNIT #154A	3003926274	BLANCO MV	113	3110	05W	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mit
ROSA UNIT #156	3004529661	BLANCO MV	9A	3110	ogw	BG1	HDPE SECONDARY LINER LIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #156A	3004529640	BLANCO MV BASIN DK /	91	3114	oew	BGT	HOPE SECONDARY LINER
ROSA UNIT #159 COM	3003925583	BLANCO MV	190	31N	05W	BGT	DBI WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #159A	3003926273	BLANCO MV	1910	3111	05W	BG+	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #15C	3003930111	BLANCO MV BLANCO MV	29G	31N	O5VV	вет	HDPE SECONDARY LINER
ROSA UNIT #160	3003925890	ROSA PC	250	31N	OGVv	BGT	DBI WALL STEEL
ROSA UNIT #160A	3003925818	BLANCO MV BASIN DK /	25N	3110	06W	BGT	DBL WALL STELL FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #160H	3003926962	BLANCO MV	251	31N	06Vv	BGT	HOPE SECONDARY LINER
ROSA UNIT #160C	3003929778	BLANCO MV	253	3110	06W	BGT	DBL WALL STEEL TIBERGLASS TANK w/BANDED 20-mil
RUSA UNIT #162	3003926069	BLANCO MV	30K	31N	05W	BGT	HDPE SECONDARY LINER
ROSA UNIT #162B	3003929845	BLANCO MV	30l ₃	3110	05W	BGT	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #163	3003926345	BLANCO MV	24G	31N	Wan	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #163A	3003926336	BLANCO MV	240	31N	06W	BGI	HDPE SECONDARY LINER
ROSA UNIT #163B	3003929921	BLANCO MV	24B	31N	06W	SGI	DBL WALL STEEL
ROSA UNIT #163C	3003929611	BLANCO MV BASIN DK /	24J	31N	06W	SG1	SINGLE WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #164	3003926151	BI ANCO MV	1.J	31N	06W	BGI	HDPE SECONDARY LINER FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #164A	3003926080	BLANCO MV BASIN DK /	1.1	31N	0674	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
KOSA UNIT #164L	3003927242	BLANCO MV	1,1	3111	06W	BG1	HDPE SECONDARY LINER

ŧ


WELLS W/FEDERAL		F 44 T		* . *			CONSTRUCTION MATERIAL
SURF MG1	<u> </u>	BLANCO MV	SEC	ĪMÑ	RNG	PILTYPE	CONSTRUCTION MATERIAL
ROSA UNIT #165	3003926070		251	.s11V	06Vv	BGT	DBL WALL STEEL FIBERGLASS TANK WBANDED ZO mid
ROSA UNIT #165A	3003926156	BLANCO MV BASIN DK /	268	31N	OGVV	BG1	HDPF SECONDARY LINER
ROSA UNIT #165B	3003926557	BLANCO MV BASIN DK /	251	3114	aavv	RGT	DBI WALL STEFI
ROSA UNIT #1650	3003926961	BLANCO MV	25G	3110	OEVV	BGT	DBI WALL STEEL LIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #166	3003926275	BLANCO MV	3()A	31N	Of-W	HGT	HDPF SECONDARY LINER LIBERGLASS TANK w/BANDED 20 mil
ROSA UNIT #166A	3003926282	BLANCO MV	301	3111	U5VV	BGT	HDPE SECONDARY LINER LIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #167A	3004529886	BLANCO MV	ЬA	3114	ÖĞVV	BGT	HDPF SECONDARY LINER
ROSA UNIT #169	3003926130	BLANČO MV	3,1	3414	OGVV	BGT	DBL WALL STEEL
ROSA UNIT #169A	3003926149	BLANCO MV	3.1	31N	06W	BGT	DBL WALL STEEL FIBERGLASS TANK w/BANDED 20-mil
ROSA UNIT #1690	3003927717	BLANCO MV	21.1	31N	OGVV	BGT	HDPE SECONDARY LINER
ROSA UNIT #170	3003925851	BLANCO MV	2114	3110	0674	BGT	DBI WALL STELL
ROSA UNEL#171	3003926286	BLANCO MV	7G	31N	06·W		DBL WALL STEEL FIBERGLASS TANK WBANDED 20 mil
ROSA UNIT #171A	3003926389	BLANCO MV	/G	3118	05Vc	BGT	HOPE SECONDARY LINER FIBERGLASS TANK WBANDED 20-mil
ROSA UNIT #171E	3003927013	BLANCO MV	6P	311/	05//	BGT	HDPE SECONDARY LINER
ROSA UNIT #180	3004529898	BLANCO MV	910	31N	OGVv		FIBERGLASS TANK W/BANDED 20 mil HDPE SECONDARY LINER
ROSA (INIT #1808	3004533134	BLANCO MV	91	3118	06/4	BGT	DBI WALL STELL
ROSA UNIT #1800	3004533191	BLANCO MV	ЯE	31N	oovv	EG1	DBI WALL STELL
ROSA UNIT #181	3003926463	BLANCO MV	11K	3111	06VV		DBL WALL STEEL FIBERGLASS TANK W/BANDED ZO mile
ROSA UNIT #181A ROSA UNIT #1810 (shared	3003926312	BLANCO MV	15A	3 IN	0674	BG1	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
w/169C)	3003927714	BLANCO MV	2M	3114	OGVV	BG1	HDPE SECONDARY LINER FIBERGLASS TANK W/BANDED 20 mil
ROSA UNIT #182	3003926283	BLANCO MV	18N	31N	051/0		HDPE SECONDARY LINER
ROSA UNIT #182A	3003926285	BLANCO MV	18P	3114	U5VV	BG1	DBI WALL STEEL
ROSA UNIT #1820	3003930180	BLANCO MV	1812	31N	05W		SINGLE WALL STEEL FIBERGLASS TANK W/BANDED 20-mil
ROSA UNIT #183	3003926387	BLANCO MV	19G	31N	05W	BGT	HDPE SECONDARY LINER FIBERGLASS TANK WBANDED 20 mil
COSA UNIT #183A	3003926386	BI ANCO MV	191	31N	U5W		HOPE SECONDARY LINER
:OSA UNIT #1838	3003930087	BLANCO MV BASIN DK /	198	31N	05W	BG1	DBI WALI STEEL
OSA UNIT #185B	3004532734	BLANCO MV	16F	31N	06W	BG1	DBI WAIL STEEL
OSA UNIT #1850	3004534484	BLANCO MV	16F	31N	06W	BG1	DBI WALL STEEL
OSA UNIT #18!	3003930186	BLANCO MV	21G	31lv	05Vr	BGT	DBL WALL STEEL


j

WELLS W/FEDERAL	a submit opinio il bi il prodrosso del							
SURF MG1	API	FM1	SEC	IWN	RNG	PIT TYPE	CONSTRUCTION	MATERIAL
ROSA UNIT #2:31	3003924444	DASINELL	1111	3114	05Vv	861	SWGLE WALL STELL	
ROSA UNIT #335A	5005930222	BASINTIC	00.5	3114	otiv	561	SINGLE WALL STELL	

)

,





04-36 Rosa Unit 180

	•									
						Liner	eak detection		Pit	
Date	WellName	Run	Formation	Construction	SGT. BGT, Above	Banded Plastic liner, Double Wall	Y/N	level	level	Comments / Repairs needed
8/28/2008	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	plastic liner	Yes	3.5	6	
9/4/2008	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	plastic liner	Yes	10.5	9.5	
10/1/2008	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES	14	14.5	
11/21/2008	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	_ NO	YES	15	17.5	
12/4/2008	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES	14	19	
1/10/2009	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES	15	14	
2/16/2009	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES	15	14	
3/19/2009	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES	18	20	
4/15/2009	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES			
5/26/2009	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES	17	28.5	
6/30/2009	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES	9	33.5	
7/29/2009	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES	12	33.5	

8/31/2009	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES	4	4	
9/11/2009	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES	5.5	5	
10/30/2009	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES	7.25	12	
	UNIT #180	04-34	Mesa Verde	FIBERGLASS	BGT	NO	YES			Pit has been removed

.