



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCUD JUN 6 '12
OIL CONS. DIV.

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DIST. 3

Date of Test 6-6-12 Operator Burlington API #30-0 45-07298
Property Name McMullan Well No. 16 Location: Unit 21 Section 28 Township 10
Well Status (Shut-In or Producing) Initial PSI: Tubing 177.7 Intermediate N/A Casing 177.3 Bradenhead 39.8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERMEDIATE		
	Bradenhead BH	Int	Csg	Int	Csg	
6.5" 5 min	6.7		178.3			
7.0" 10 min	7.0		178.5			
7.5" 15 min	8.0		178.8			
8" 20 min	6.5		179.			
8.5" 25 min	5.6		179.3			
9" 30 min	4.7		179.6			

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	☒	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water	☒	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☒ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 34.3

INTERMEDIATE N/A

REMARKS: 6" in p.t. to start 9" at end of 30 minute test.
Well was running 13 gallons in 5 min. flowed
Water whole 30 min.

By Brian Van Caster

Witness Marcia Kuehling

(Position)

E-mail address _____