



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III3district.htm](http://emnr.state.nm.us/ocd/District%20III3district.htm)

RCVD JUN 5 '12
OIL CONS. DIV.

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DIST. 3

Date of Test 6/5/2012 Operator Burington API #30-039-30866

Property Name San Juan 24-7 unit Well No. 75M Location: Unit 6 Section 23 Township 29 Range 7

Well Status (Shut-In) or Producing) Initial PSI: Tubing 200 Intermediate 0 Casing 191 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	191	0	191
10 min	0	0	191	0	191
15 min	0	0	191	0	191
20 min	1	1	1	1	1
25 min	1	1	1	1	1
30 min	1	1	1	1	1

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X X
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

Intermediate down in 15 sec, no LEL or H₂S or fluids, BH puff 5 sec
blow down 1" valve on both.

By

Juniper D Birdsey

(Position)

Witness

Jonathan D. Kelly

E-mail address _____