



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

RCVD JUN 19 '12

OIL CONS. DIV.

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-19-12 Operator Burlington Res API #30-0 45-21042

Property Name Stambling A Well No. 7 Location: Unit Section 22 Township 28 Range 8

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing ✓ Intermediate ✓ Casing 24 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		32		
10 min	0		34		
15 min	0		36		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE ✓

REMARKS: This is a slimhole. Produces out of casing
puff when opened through hose (were expecting water - no
water) reading 1 second.

By Robert Chavez

Witness Monica Calkins

(Position)

E-mail address