

District I  
1625 N French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

X Initial Report ☒ Final Report

Name of Company Mallon Oil Company	Contact Ron Sansoni
Address P. O. Box 2797 Durango, CO 81302	Telephone No. 970-382-9100
Facility Name Jicarilla 30-03-28 No. 2	Facility Type Gas Well

Surface Owner Jicarilla Apache Tribe	Mineral Owner Mallon Oil Company	Lease No. 30-3-28
---	-------------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 28	Township 30N	Range 03W	Feet from the 874'	North/South Line North	Feet from the 790'	East/West Line West	County Rio Arriba
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------------

NATURE OF RELEASE

Type of Release Produced Formation Water	Volume of Release 60 bbls	Volume Recovered 60 bbls
Source of Release Tank Overflow	Date and Hour of Occurrence 7/15/00 - 6:00 pm 7/16/00 - 8:00 am	Date and Hour of Discovery 7/16/00 - 9:00 am
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Charlie Perrin - Aztec OCD	
By Whom? Jim Costalez	Date and Hour July 16, 2000 9:00 AM - July 19, 2000 9:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
Did not overflow berm around tank.

Describe Cause of Problem and Remedial Action Taken.\*

The well was unloaded to the tank the afternoon of the July 15, 2000. The well was still unloading strong when well was put on production. The water hauling company assigned to pull the production water was called to work another job. A breakdown in communication occurred at this point. A notice will be sent to the field personnel stating to not interrupt critical operations without notifying a Mallon supervisor.


Describe Area Affected and Cleanup Action Taken.\*

The berm was emptied and area of spill cleared.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Ronald Sansoni</i>	OIL CONSERVATION DIVISION	
Printed Name: Ronald Sansoni	Approved by <i>Wendy Faint</i>	
Title: District Production Superintendent	District Supervisor: <i>for Frank Chavez</i>	
Date: 7/26/00	Approval Date: <i>8/01/00</i>	Expiration Date:
Phone: 970-382-9100	Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary



Not in computer

nJK1217251663