

District I - (505) 393-6161
P. O. Box 1980
Hobbs, NM 88241-1980
District II - (505) 748-1283
811 South First
Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Road
Aztec, NM 87410
District IV - (505) 827-7131

State of New Mexico
Energy Minerals and Natural Resources Department
Oil Conservation Division
2040 South Pacheco Street
Santa Fe, New Mexico 87505
505-827-7131

Form C-141
Originated 2/13/97

Submit 2 copies to
Appropriate District
Office in accordance
with Rule 116 on
back side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report

☒ Final Report

Name Central Resources, Inc.	Contact Rodney L. Seale
Address PO Box 1247, Bloomfield, NM 87413	Telephone No. 505-632-3476
Facility Name South Bisti 30-N No. 1	Facility Type Tank Battery

Surface Owner unk	Mineral Owner BLM	Lease No. NM-80507
----------------------	----------------------	-----------------------

LOCATION OF RELEASE

Unit Letter N	Section 30	Township 26N	Range 13W	Feet From the 660	North/South Line South	Feet From the 1980	East/West Line West	County San Juan
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	--------------------

NATURE OF RELEASE

Type of Release Oil	Volume of Release 8	Volume Recovered 0
Source of Release Tank Battery	Date and Hour of Occurrence 2-22-00, unk	Date and Hour of Discovery 2-22-00, unk
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mark Kelley, BLM; Attempted OCD, but got tired of going down the call list	
By Whom? Rod Seale	Date and Hour 2-22-00, 4:45 PM	
Was Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)


Stayed proximal to location.

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Water dump plugged, tank equalizer plugged.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

Remediate on Site. There was no free liquid to recover.



I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate Contamination that poses a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rodney L. Seale</i>	OIL CONSERVATION DIVISION	
Rodney L. Seale Printed Name:	Approved by: <i>Frank Chavez</i> District Supervisor:	
Title: District Manager	Approval Date: 2/28/2000	Expiration Date:
Date: February 22, 2000 Phone: 505-632-3476	Conditions of Approval:	Attached <input type="checkbox"/>

nJK1217255949

Not entered in computer