

District I - (505) 393-6161

P.O. Box 1940

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

## State of New Mexico


## Energy Minerals and Natural Resources Department

## Oil Conservation Division

2040 South Pacheco Street

Santa Fe, New Mexico 87505

(505) 827-7131

Form C-141  
Originated 2/13/97Submit 2 copies to:  
Appropriate District  
Office in accordance  
with Rule 116.

## Release Notification and Corrective Action

## OPERATOR

30-045-2905

Name:	Burlington Resources	Contact:	Ed Hasely
Address:	P.O. Box 4289 Farmington NM 87499	Telephone No.:	(505) 326-9537
Facility Name:	JOHNSTON FEDERAL 30	Facility Type:	Gas Well

Surface Owner:	Federal	Mineral Owner:	Federal	Lease Number:	NMSF-078439
----------------	---------	----------------	---------	---------------	-------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet From the	North/South Line	Feet From the	East/West Line	County: San Juan
O	35	031N	009W	1180	South	1605	East	

## NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	20 bbls.	Volume Recovered:	15 bbls.
Source of Release:	Water Storage Tank	Date and Hour of Occurrence:	1/9/00	Date and Hour of Discovery:	1/9/00
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If Yes, To Whom?			
By Whom?	Date and Hour:				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. 0			

If a Watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)

NA

Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets If Necessary)

Produced water storage tank overflowed. Water truck broke down over the weekend and did not make it to location in time.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets If Necessary)

All fluids were contained inside the tank berms. A vacuum truck was used to recover the free liquids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	Approved by	District Supervisor:	
Title: Environmental Representative	Approval Date:	Expiration Date:	
Date: 1/10/00 Phone: (505) 326-9841 or 326-9842	Conditions of Approval:	Attached: <input type="checkbox"/>	

nJK 1217252150