

District I
1625 N. French Dr., Hobbs, NM 88240
District II
311 South First, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
2040 South Pacheco
Santa Fe, NM 87505

Form C-141
Revised March 17, 1999

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

30-039-23367

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company <i>nm + O Operating</i>	Contact <i>Hap Post</i>
Address <i>6 E 5th, Suite 200 - Tulsa, OK 74103</i>	Telephone No. <i>(505) 774-6584</i>
Facility Name <i>Gavilan #2</i>	Facility Type <i>Gas + Oil Well</i>

Surface Owner <i>L. J. Ingram</i>	Mineral Owner	Lease No. <i>081296</i>
--------------------------------------	---------------	----------------------------

LOCATION OF RELEASE

Unit Letter	Section <i>26</i>	Township <i>25N</i>	Range <i>2W</i>	Feet from the	North/South Line	Feet from the	East/West Line	County <i>Rio Arriba</i>
-------------	----------------------	------------------------	--------------------	---------------	------------------	---------------	----------------	-----------------------------

NW 1/4 SE 1/4

NATURE OF RELEASE

Type of Release <i>Oil</i>	Volume of Release <i>55 bbls.</i>	Volume Recovered <i>20 bbls</i>
Source of Release <i>Oil tank</i>	Date and Hour of Occurrence <i>4/4/00</i>	Date and Hour of Discovery <i>4/4/00 4:00pm?</i>
Was Immediate Notice Given? ☒ Yes ☐ No ☐ Not Required	If YES, To Whom? <i>DANETTE W/BLM Office in Cuba</i>	
By Whom? <i>Hap Post</i>	Date and Hour <i>4/5/00</i>	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Water dump failed causing all the water to go to the oil tank - well makes approx. 150 bbls of water a day. I shut the well in - retrieved oil from fire wall

Describe Area Affected and Cleanup Action Taken.*

Grassy hillside - spread dirt over stained soil per rancher's request. This is the clean-up method the Rancher/landowner demanded.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Elvin (Hap) Post</i>		OIL CONSERVATION DIVISION	
Printed Name: <i>Elvin (Hap) Post</i>		Approved by: <i>Wendy Fourn</i> District Supervisor: <i>for Frank Chaez</i>	
Title: <i>Operator</i>		Approval Date: <i>4/27/00</i>	Expiration Date:
Date: <i>4/14/00</i>	Phone: <i>(505) 774-6584</i>	Conditions of Approval: <i>Operator will file one page summary of water filling remediation</i>	Attached ☐

* Attach Additional Sheets If Necessary

n CTP 0000008