

District I - (505) 393-6161  
P O Box 1980

Hobbs, NM 88241-1980

District II - (505) 748-1283

811 South First

Artesia, NM 88210


District III - (505) 334-6178

1000 Rio Brazos Road

Aztec, NM 87410

District IV - (505) 827-7131

State of New Mexico  
Energy Minerals and Natural Resources Department  
Oil Conservation Division  
2040 South Pacheco Street  
Santa Fe, New Mexico 87505  
(505) 827-7131



Form C - 141  
Originated 2/13/97

Submit 2 copies to  
Appropriate District  
Office in accordance  
with Rule 116 on  
back side of form

30-045-27935

Release Notification and Corrective Action  
OPERATOR

Name <b>Phillips Petroleum Company</b>	Contact <b>Robert A. Wirtanen</b>
Address <b>5525 Hwy. 64, Farmington, New Mexico 87401</b>	Telephone Number <b>(505) 599-3462</b>
Facility Name <b>San Juan 32-8 Unit: Well #301</b>	Facility Type <b>SWD</b>

Surface Owner <b>State</b>	Mineral Owner <b>State</b>	Lease No <b>E-5113-21</b>
		API # <b>30-045-27935</b>

LOCATION OF RELEASE

Unit Letter <b>L</b>	Section <b>16</b>	Township <b>31N</b>	Range <b>8W</b>	Feet from the <b>1643'</b>	North/South Line <b>South</b>	Feet from the <b>1006'</b>	East/West Line <b>West</b>	County <b>San Juan</b>
-------------------------	----------------------	------------------------	--------------------	-------------------------------	----------------------------------	-------------------------------	-------------------------------	---------------------------

NATURE OF RELEASE

Type of Release <b>Produced Water</b>	Volume of Release <b>90 BBLs</b>	Volume Recovered <b>80 BBLs</b>
Source of Release <b>Tank #10 overflowed.</b>	Date & Hour of Occurrence <b>3/11/00</b>	Date & Hour of Discovery <b>3/11/00 0737 hr.</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>NMOCD - by tele-fax</b>	
By Whom? <b>Robert A. Wirtanen</b>	Date and Hour <b>3/13/00 1000 hr.</b>	
Was a Watercourse Reached? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	If YES, Volume Impacting the Watercourse <b>No spilled water impacted a watercourse</b>	
If a Watercourse was impacted, describe fully. (Attach additional sheets if necessary) <b>na</b>		

Describe cause of problem and remedial action taken (attach additional sheets if necessary)

**Water was discovered inside the diked area. The discharge injection pumps to the well shut down. This caused the tank to overflow. In addition, the high-level shut-down switch on the tank did not function, which should have prevented the incident.**

Describe area affected and cleanup action taken (Attach additional sheets if necessary)

**80 BBLs were recovered by pump truck and replaced into the water tanks for disposal into the on-site well.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the Operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature <i>RAW</i>	OIL CONSERVATION DIVISION Approved by <i>Denny G. Hunt</i> District Supervisor <i>for Frank Chavez</i>	
Printed Name <b>Robert A. Wirtanen</b>	Approval Date <b>3/15/00</b>	Expiration Date
Title <b>Sr. Safety &amp; Environmental Specialist</b>	Conditions of Approval	Attached <input type="checkbox"/>
Date <b>3/13/00</b>	Phone <b>(505) 599-3462</b>	

Not in computer  
nJK 1217335430