District I

1625 N French Dr , Hobbs, NM 88240

District II 1301 W Grand Ave , Artesia, NM 88210 District III

1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico Energy Minerals and Natural Resources

Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-144 July 21, 2008

For temporary pits, closed-loop sytems, and below-grade tanks, submit to the appropriate NMOCD District Office

For permanent pits and exceptions submit to the Santa Fe

District IV 1220 S St Francis Dr., Santa Fe, NM 87505			opriate NMOCD District Office		
	Pit, Closed-Loop System	, Below-Grade Ta	ınk, or		
	sed Alternative Method I				
Type of action: [Type of action: Permit of a pit, closed-loop system, below-grade tank, or proposed alternative method				
	X Closure of a pit, closed-loop sy	stem, below-grade tank, o	or proposed alternative method		
[Modification to an existing per	mit			
[Closure plan only submitted for below-grade tank, or proposed	0.	non-permitted pit, closed-loop system,		
Instructions: Please submit one app	lication (Form C-144) per individ	dual pit, closed-loop syste	em, below-grade tank or alternative request		
··	•	- ,	pollution of surface water, ground water or the nental authority's rules, regulations or ordinances		
1 Operator: Burlington Resources Oil 6	& Gas Company, LP	OGR	UD#: <u>14538</u>		
Address P.O. Box 4289, Farmington	ı, NM 87499				
Facility or well name SAN JUAN 27	-4 UNIT 28C				
API Number 30-	039-30589	OCD Permit Number			
U/L or Qtr/Qtr: C(NE/NW) Section	· 11 Township 27N	Range 4W	County. Rio Arriba		
Center of Proposed Design Latitude	36.592318 °N		223494 °W NAD. 1927 X 1983		
Surface Owner X Federal	State PrivateT	ribal Trust or Indian Allo	tment		
	vitation P&A or type Thickness 12 mil	X LLDPE HDPE Volume 4400 bbl	Dimensions L <u>65'</u> x W <u>45'</u> x D <u>10'</u>		
	n H of 19 15 17 11 NMAC Drilling a new well Workover o	•	ies which require prior approval of a permit or		
Drying Pad Above Ground	Steel Tanks Haul-off Bins	Other			
Lined Unlined Liner t	ype Thicknessmil	LLDPE HDPE	PVD Other 345678970		
Liner Seams Welded Fact	tory Other	-			
4					
Below-grade tank: Subsection I o	f 19 15 17 11 NMAC		overflow shut-off		
Volumebbl	Type of fluid		— / cons one		
Tank Construction material			overflow shut-off CSE PSES ZZ LZ OZ		
Secondary containment with leak deter		er, 6-inch lift and automatic o	overflow shut-off		
Usible sidewalls and liner Liner Type Thickness	Visible sidewalls only \(\bigcup O \) mil \(\bigcup HDPE \bigcup PVC \)	Other	27222324		
Linei Type Thickness		Other			
5 Alternative Method:					
_	red Exceptions must be submitted to	the Santa Fe Environmental	Bureau office for consideration of approval		
Daoinitiai of an exception request is requi	.va Exceptions must be submitted to	and contract of Physical Child	Darvas office for consideration of approval		

6 ' '					
Fencing: Subsection D of 19 15 17 11 NMAC (Applies to permanent pit, temporary pits, and below-grade tanks)					
Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, hospital, institution or church)					
Four foot height, four strands of barbed wire evenly spaced between one and four feet Alternate Please specify					
Attendate 1 lease specify					
Netting: Subsection E of 19 15 17 11 NMAC (Applies to permanent pits and permanent open top tanks)					
Screen Netting Other Name of the Control of the Co					
Monthly inspections (If netting or screening is not physically feasible)					
8					
Signs: Subsection C of 19 15 17 11 NMAC 12" X 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers					
X Signed in compliance with 19 15 3 103 NMAC		1			
A Signed in compliance with 19 19 3 103 NWAC					
9 Administrative Approvals and Expertions.					
Administrative Approvals and Exceptions: Justifications and/or demonstrations of equivalency are required Please refer to 19 15 17 NMAC for guidance					
Please check a box if one or more of the following is requested, if not leave blank:					
Administrative approval(s) Requests must be submitted to the appropriate division district of the Santa Fe Environmental Bureau office for cons	ideration of ap	proval			
(Fencing/BGT Liner)					
Exception(s) Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval		:			
10					
Siting Criteria (regarding permitting) 19 15 17 10 NMAC					
Instructions. The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the		İ			
appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau Office for					
consideration of approval. Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria		ļ			
does not apply to drying pads or above grade-tanks associated with a closed-loop system.					
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank.	Yes	No			
- NM Office of the State Engineer - IWATERS database search, USGS, Data obtained from nearby wells					
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other watercourse, lakebed, sinkhole, or playa lake	Yes	□No			
(measured from the ordinary high-water mark). - Topographic map, Visual inspection (certification) of the proposed site		1			
		_			
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.	Yes	∐No			
(Applies to temporary, emergency, or cavitation pits and below-grade tanks)					
- Visual inspection (certification) of the proposed site, Aerial photo, Satellite image	⊔''''				
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.	Yes	Пио			
(Applied to permanent pits)					
- Visual inspection (certification) of the proposed site, Aerial photo, Satellite image	∐ ^{NA}				
Within 500 horizonal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering	Yes	□No			
purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application.					
NIMOSS CALSO S WATERS LATE AND A COMMING A COMMING AND A C					
- NM Office of the State Engineer - iWATERS database search, Visual inspection (certification) of the proposed site					
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended	Yes	∐No			
- Written confirmation or verification from the municipality, Written approval obtained from the municipality					
Within 500 feet of a wetland.	Yes	□No			
- US Fish and Wildlife Wetland Identification map, Topographic map, Visual inspection (certification) of the proposed site					
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD - Mining and Mineral Division	Yes	□No			
·					
Within an unstable area. - Engineering measures incorporated into the design, NM Bureau of Geology & Mineral Resources, USGS, NM Geological	Yes	∐No			
Society, Topographic map					
Within a 100-year floodplain	Yes	No			
- FFMΔ man	r	1			

Temporary Pits, Emergency Pits and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19 15 17 9 NMAC				
Instructions Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached				
Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19 15 17 9 NMAC				
Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19 15 17 9				
Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC				
Design Plan - based upon the appropriate requirements of 19 15 17 11 NMAC				
Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC				
Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15 17 13 NMAC				
Previously Approved Design (attach copy of design) API or Permit				
12				
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19 15 17 9 NMAC Instructions Each of the following items must be attached to the application Please indicate, by a check mark in the box, that the documents are attached Geologic and Hydrogeologic Data (only for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of 19 15 17 9				
Siting Criteria Compliance Demonstrations (only for on-site closure) - based upon the appropriate requirements of 19 15 17 10 NMAC				
Design Plan - based upon the appropriate requirements of 19 15 17 11 NMAC				
Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC				
Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 15 17 9				
NMAC and 19 15 17 13 NMAC				
Previously Approved Design (attach copy of design) API				
Previously Approved Operating and Maintenance Plan API				
13				
Permanent Pits Permit Application Checklist: Subsection B of 19 15 17 9 NMAC				
Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the documents are attached.				
Hydrogeologic Report - based upon the requirements of Paragraph (I) of Subsection B of 19 15 17 9 NMAC				
Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19 15 17 10 NMAC				
Climatological Factors Assessment				
Certified Engineering Design Plans - based upon the appropriate requirements of 19 15 17 11 NMAC				
Dike Protection and Structural Integrity Design based upon the appropriate requirements of 19 15 17 11 NMAC				
Leak Detection Design - based upon the appropriate requirements of 19 15 17 11 NMAC				
Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19 15 17 11 NMAC Quality Control/Quality Assurance Construction and Installation Plan				
Operating and Maintenance Plan - based upon the appropriate requirements of 19 15 17 12 NMAC				
Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19 15 17 11 NMAC				
Nuisance or Hazardous Odors, including H2S, Prevention Plan				
Emergency Response Plan				
Oil Field Waste Stream Characterization				
Monitoring and Inspection Plan				
Erosion Control Plan				
Closure Plan - based upon the appropriate requirements of Subsection C of 19 15 17 9 NMAC and 19 15 1713 NMAC				
14				
Proposed Closure: 19 15 17 13 NMAC				
Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Closed-loop System				
Alternative				
Proposed Closure Method Waste Excavation and Removal				
Waste Removal (Closed-loop systems only)				
On-site Closure Method (only for temporary pits and closed-loop systems)				
In-place Burial On-site Trench				
Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for consideration)				
15				
Waste Excavation and Removal Closure Plan Checklist: (19 15 17 13 NMAC) Instructions: Each of the following items must be attached to the closure plan.				
Please indicate, by a check mark in the box, that the documents are attached.				
Protocols and Procedures - based upon the appropriate requirements of 19 15 17 13 NMAC				
Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC				
Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings)				
Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19 15 17 13 NMAC				
Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15 17 13 NMAC				
Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19 15 17 13 NMAC				

16 Waste Removal Closure For Closed-loop Systems That Utilize Above Ground St Instructions Please identify the facility or facilities for the disposal of liquids, drilli				
facilities are required	and and an arm comment of the arms of the			
Disposal Facility Name	Disposal Facility Permit #			
Disposal Facility Name	Disposal Facility Permit #			
Will any of the proposed closed-loop system operations and associated activity Yes (If yes, please provide the information No	ties occur on or in areas that will not be used for future	service and		
Required for impacted areas which will not be used for future service and operation Soil Backfill and Cover Design Specification - based upon the appropriate requirements of Subs Site Reclamation Plan - based upon the appropriate requirements of Si	rrate requirements of Subsection H of 19 15 17 13 NMa section I of 19 15 17 13 NMAC	4C		
Site Reciamation Fian - based upon the appropriate requirements of Si	ubsection G of 19 13 17 13 NMAC			
17 Siting Criteria (Regarding on-site closure methods only: 19 15 17 10 NMs Instructions Each siting criteria requires a demonstration of compliance in the closure pla certain siting criteria may require administrative approval from the appropriate district off office for consideration of approval Justifications and/or demonstrations of equivalency a	m Recommendations of acceptable source material are provided fice or may be considered an exception which must be submitted to			
Ground water is less than 50 feet below the bottom of the buried waste		Yes No		
- NM Office of the State Engineer - IWATERS database search, USGS Data of	btained from nearby wells	∐N/A		
Ground water is between 50 and 100 feet below the bottom of the buried was	ste	Yes No		
- NM Office of the State Engineer - 1WATERS database search, USGS, Data ob	stained from nearby wells	□N/A		
Ground water is more than 100 feet below the bottom of the buried waste		∏Yes ∏No		
- NM Office of the State Engineer - IWATERS database search, USGS, Data ob	stained from nearby wells	N/A □		
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other signif (measured from the ordinary high-water mark)	ficant watercourse or lakebed, sınkhole, or playa lake	Yes No		
- Topographic map, Visual inspection (certification) of the proposed site				
Within 300 feet from a permanent residence, school, hospital, institution, or church in - Visual inspection (certification) of the proposed site, Aerial photo, satellite image		Yes No		
,		Yes No		
Within 500 horizontal feet of a private, domestic fresh water well or spring that less the purposes, or within 1000 horizontal fee of any other fresh water well or spring, in exist. - NM Office of the State Engineer - iWATERS database, Visual inspection (certical contents).	stence at the time of the initial application			
Within incorporated municipal boundaries or within a defined municipal fresh water v pursuant to NMSA 1978, Section 3-27-3, as amended		Yes No		
Written confirmation or verification from the municipality, Written approval ob Within 500 feet of a wetland	tained from the municipality			
- US Fish and Wildlife Wetland Identification map, Topographic map, Visual ins	spection (certification) of the proposed site			
Within the area overlying a subsurface mine		Yes No		
- Written confirantion or verification or map from the NM EMNRD-Mining and	Mineral Division			
Within an unstable area		∐Yes ∐No		
Engineering measures incorporated into the design, NM Bureau of Geology & N Topographic map	Mineral Resources, USGS, NM Geological Society,			
Within a 100-year floodplain - FEMA map		Yes No		
18 On-Site Closure Plan Checklist: (19 15 17 13 NMAC) Instructions: Each by a check mark in the box, that the documents are attached.	h of the following items must bee attached to the closs	ure plan. Please indicate,		
Siting Criteria Compliance Demonstrations - based upon the appropria	ate requirements of 19 15 17 10 NMAC			
Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection F of 19 15 17 13 NMAC				
Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of 19 15 17 11 NMAC				
Construction/Design Plan of Temporary Pit (for in place burial of a dr		19 15 17 11 NMAC		
Protocols and Procedures - based upon the appropriate requirements of		., ., ., ., ., ., ., ., ., ., ., ., ., .		
Confirmation Sampling Plan (if applicable) - based upon the appropria				
Waste Material Sampling Plan - based upon the appropriate requirement				
Disposal Facility Name and Permit Number (for liquids, drilling fluid:		annot be achieved)		
Soil Cover Design - based upon the appropriate requirements of Subse	ection H of 19 15 17 13 NMAC	aunor de aemeveu)		
Re-vegetation Plan - based upon the appropriate requirements of Subsection I of 19 15 17 13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection G of 19 15 17 13 NMAC				

19 On any ten Application Could Station
Operator Application Certification: 1 hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and belief
Name (Print) Title
Signature Date
e-mail address Telephone
OCD Approval: Permit Application (including closure plan) Closure Riam (only) OCD Conditions (see attachment) OCD Representative Signature: Approval Date: OCD Permit Number:
21
Closure Report (required within 60 days of closure completion): Subsection K of 19 15 17 13 NMAC Instructions Operators are required to obtain an approved closure plan prior to implementing any closure activities and submitting the closure report. The closure report is required to be submitted to the division within 60 days of the completion of the closure activities. Please do not complete this section of the form until an approved closure plan has been obtained and the closure activities have been completed.
X Closure Completion Date: October 19, 2009
22 Closure Method: Waste Excavation and Removal X On-site Closure Method Alternative Closure Method Waste Removal (Closed-loop systems only) If different from approved plan, please explain
23
Closure Report Regarding Waste Removal Closure For Closed-loop Systems That Utilize Above Ground Steel Tanks or Haul-off Bins Only:
Instructions. Please identify the facility or facilities for where the liquids, drilling fluids and drill cuttings were disposed Use attachment if more than two facilities were utilized.
Disposal Facility Name Disposal Facility Permit Number
Disposal Facility Name Disposal Facility Permit Number
Were the closed-loop system operations and associated activities performed on or in areas that will not be used for future service and operations?
Yes (If yes, please demonstrate compliane to the items below)
Required for impacted areas which will not be used for future service and operations Site Reclamation (Photo Documentation)
Soil Backfilling and Cover Installation
Re-vegetation Application Rates and Seeding Technique
24
Closure Report Attachment Checklist: Instructions Each of the following items must be attached to the closure report. Please indicate, by a check mark in
the box, that the documents are attached
X Proof of Closure Notice (surface owner and division) X Proof of Deed Notice (required for on-site closure)
X Plot Plan (for on-site closures and temporary pits)
X Confirmation Sampling Analytical Results (if applicable)
Waste Material Sampling Analytical Results (if applicable)
X Disposal Facility Name and Permit Number
X Soil Backfilling and Cover Installation
X Re-vegetation Application Rates and Seeding Technique
X Site Reclamation (Photo Documentation)
On-site Closure Location Latitude <u>36.59217</u> °N Longitude <u>107.2234</u> °W NAD 1927 X 1983
25 O
Operator Closure Certification: I hereby certify that the information and attachments submitted with this closure report is ture, accurate and complete to the best of my knowledge and belief 1 also certify that
the closure complies with all applicable closure requirements and conditions specified in the approved closure plan
Name (Print) Crystal Tafoya Title Regulatory Tech
Signature Instal Talaya Date 2/8/2010
e-mail address crystal tafoya@conocophillips.com Telephone 505-326-9837

Burlington Resources Oil Gas Company, LP San Juan Basin Closure Report

Lease Name: SAN JUAN 27-4 UNIT 28C

API No.: 30-039-30589

In accordance with Rule 19.15.17.13 NMAC the following information describes the closure of the temporary pit referenced above. All proper documentation regarding closure activities is being included with the C-144. The temporary pit for this location was constructed and location drilled before June 16, 2008 (effective date for Rule 19.15.17). While closure of the temporary pit did fall within the rule some dates for submittals are after the rig release date.

- Details on Capping and Covering, where applicable. (See report)
- Plot Plan (Pit Diagram) (Included as an attachment)
- Inspection Reports (Included as an attachment)
- Sampling Results (Included as an attachment)
- C-105 (Included as an attachment)
- Copy of Deed Notice will be filed with County Clerk (Not required on Federal, State, or Tribal land as stated by FAQ dated October 30, 2008)

General Plan:

1. All free standing liquids will be removed at the start of the pit closure process from the pit and disposed of in a division—approved facility or recycle, reuse or reclaim the liquids in a manner that the appropriate division district office approves.

All recovered liquids were disposed of at Basin Disposal (Permit #NM-01-005) and any sludge or soil required to be removed to facilitate closure was hauled to Envirotech Land Farm (Permit #NM-01-011) and JFJ Landfarm % IEI (Permit #NM-01-0010B).

2. The preferred method of closure for all temporary pits will be on-site burial, assuming that all the criteria listed in sub-section (B) of 19.15.17.13 are met.

The pit was closed using onsite burial.

3. The surface owner shall be notified of BR's closing of the temporary pit as per the approved closure plan using certified mail, return receipt requested.

The closure process notification to the landowner was sent via email. (See Attached)(Well located on Federal Land, certified mail is not required for Federal Land per BLM/OCD MOU.)

4. Within 6 months of the Rig Off status occurring BR will ensure that temporary pits are closed, re-contoured, and reseeded.

Provision 4 of the closure plan requirements were not met due to rig move off date as noted on C-105 which was prior to pit rule change. Burlington will ensure compliance with this rule in the future.

- 5. Notice of Closure will be given to the Aztec Division office between 72 hours and one week of closure via email, or verbally. The notification of closure will include the following:
 - i. Operator's name
 - ii. Location by Unit Letter, Section, Township, and Range. Well name and API number.

Notification is attached.

6. Liner of temporary pit shall be removed above "mud level" after stabilization. Removal of liner will consist of manually or mechanically cutting liner at mud level and removing all remaining liner. Care will be taken to remove "All" of the liner i.e., edges of liner entrenched or buried. All excessive liner will be disposed of at a licensed disposal facility.

Liner of temporary pit was removed above "mud level" after stabilization. Removal of the liner consisted of manually cutting liner at mud level and removing all remaining liner. Care was taken to remove "ALL" of the liner i.e., edges of liner entrenched or buried. All excessive liner was disposed of at a licensed disposal facility, (San Juan County Landfill).

7. Pit contents shall be mixed with non-waste containing, earthen material in order to achieve the solidification process. The solidification process will be accomplished using a combination of natural drying and mechanically mixing. Pit contents will be mixed with non-waste, earthen material to a consistency that is deemed a safe and stable. The mixing ratio shall not exceed 3 parts clean soil to 1 part pit contents.

Burlington mixed the Pit contents with non-waste containing, earthen material in order to achieve the solidification process. The solidification process was accomplished by using a combination of natural drying and mechanically mixing. Pit contents were mixed with non-waste, earthen material to a consistency that is deemed as safe and stable. The mixing ratio consisted of approximately 3 parts clean soil to 1 part pit contents.

8. A five point composite sample will be taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17 13(B)(1)(b). In the event that the criteria are not met, all contents will be handled per Subparagraph (a) of Paragraph (1) of Subsection B of 19.15.17.13 i.e., Dig and haul.

A five point composite sample was taken of the pit using sampling tools and all samples tested per Subsection B of 19.15.17.1 3(B)(1)(b). (Sample results attached).

Components	Tests Method	Limit (mg/Kg)	Results
Benzene	EPA SW-846 8021B or 8260B	0.2	9.2 ug/kg
BTEX	EPA SW-846 8021B or 8260B	50	759 ug/kG
TPH	EPA SW-846 418.1	2500	276 mg/kg
GRO/DRO	EPA SW-846 8015M	500	88.8 mg/Kg
Chlorides	EPA 300.1	1000/500	515 mg/L

The pit material passed solidification and testing standards. The pit area was then backfilled with compacted, non-waste containing, earthen material. More than four feet of cover was achieved and the cover included one foot of suitable material to establish vegetation at the site.

10. During the stabilization process if the liner is ripped by equipment the Aztec OCD office will be notified within 48 hours and the liner will be repaired if possible. If the liner can not be repaired then all contents will be excavated and removed.

The integrity of the liner was not damaged in the pit closure process.

11. Dig and Haul Material will be transported to the Envirotech Land Farm located 16 miles south of Bloomfield on Angel Peak Road, CR 7175. Permit # NM010011

Dig and Haul was not required.

12. Re-contouring of location will match fit, shape, line, form and texture of the surrounding. Re-shaping will include drainage control, prevent ponding, and prevent erosion. Natural drainages will be unimpeded and water bars and/or silt traps will be place in areas where needed to prevent erosion on a large scale. Final recontour shall have a uniform appearance with smooth surface, fitting the natural landscape.

The pit area was re-contoured to match fit, shape, line, form and texture of the surrounding area. Reshaping included drainage control, to prevent ponding and erosion. Natural drainages were unimpeded and water bars and/or silt traps were placed in areas where needed to prevent erosion on a large scale. Final recontour has a uniform appearance with smooth surface, fitting the natural landscape.

13. Notification will be sent to OCD when the reclaimed area is seeded.

Provision 13 was accomplished through complying with Forest seeding requirements as allowed by the BLM/OCD MOU.

14. BR shall seed the disturbed areas the first growing season after the operator closes the pit. Seeding will be accomplished via drilling on the contour whenever practical or by other division-approved methods. BLM or Forest Service stipulated seed mixes will used on federal lands. Vegetative cover will equal 70% of the native perennial vegetative cover (un-impacted) consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintain that cover through two successive growing seasons. Repeat seeding or planting will be continued until successful vegetative growth occurs.

Provision 14 was accomplished through complying with Forest seeding requirements as allowed by the BLM/OCD MOU.

15. The temporary pit will be located with a steel marker, no less than four inches in diameter, cemented in a hole three feet deep in the center of the onsite burial upon the abandonment of all the wells on the pad. The marker will be flush with the ground to allow access of the active well pad and for safety concerns. The marker will include a threaded collar to be used for future abandonment. The top of the marker will contain a welded steel 12" square plate that indicates the onsite burial of the temporary pit. The plate will be easily removable and a four foot tall riser will be threaded into the top of the collar marker and welded around the base with the operator's information at the time of all wells on the pad are abandoned. The operator's information will include the following: Operator Name, Lease Name, Well Name and number, Unit Number, Section, Township, Range and an indicator that the marker is an onsite burial location.

Provision 15 was accomplished by installing a steel marker in the temporary pit, no less than four inches in diameter, cemented in a hole three feet deep in the center of the onsite burial. The marker is flush with the ground to allow access of the active well pad and for safety concerns. The top of the marker contains a welded steel 12" square plate that indicates the onsite burial of the temporary pit. The plate contains the following: Operator Name, Lease Name, Well Name and number, Unit Number, Section, Township, Range and an indicator that the marker is an onsite burial location.

The plate will be easily removable and a four foot tall riser will be threaded into the top of the collar marker and welded around the base with the following operator's information at the time of all wells on the pad are abandoned. The riser will be labeled: BR, BLM, SJ 27-4 UNIT 28C, UL-C, Sec. 11, T 27N, R 4W, API # 30-039-30589

Tafoya, Crystal

From:

Tafoya, Crystal

Sent:

Tuesday, October 28, 2008 2:29 PM

To:

'mark_kelly@nm.blm.gov'; 'jimmy_dickerson@nm.blm.gov'; 'jreidinger@fs.fed.us'

Subject:

Surface Owner Notification

The following well locations temporary pit will be closed on-site. Please let me know if you have any questions.

San Juan 30-6 Unit 36N San Juan 27-4 Unit 154N San Juan 27-4 Unit 154C San Juan 27-4 Unit 154M San Juan 27-4 Unit 28C

Thank you,

Crystal L. Tafoya Regulatory Technician ConocoPhillips Company San Juan Business Unit Phone: (505) 326-9837

Email: Crystal.Tafoya@conocophillips.com

State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505


Form C-102 Revised October 12, 2005 Submit to Appropriate District Office State Lease - 7 Copies Fee Lease - 3 Copies

MAMMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT


l Al	PI Number		2	Pool Code		³ Pool Name MESAVERDE			
⁴ Property Code	£		5 Property Name SAN JUAN 27-4 UNIT					⁶ Well Number 28C	
7 OGRID No			BURL	INGTON	8 Operator Name N RESOURCES OIL AND GAS COMPANY LP			⁹ Elevation 7156	
					10 SURFACE	LOCATION			
JL or lot no.	Section	Township	Range	Lot Ido	Feet from the	North/South line	Feet from the	East/West line	County
c	11	27-N	4-W		910	NORTH	1870	WEST	RIO ARRIBA
			" E	Sottom H	ole Location	If Different Fro	om Surface		
Ler hot no.	Section	Township	Range	Lot Ido	Feet from the	North/South line	Feet from the	East/West line	County
κ (11	27-N	4-W		2590	SOUTH	1780	WEST	RIO ARRIBA
Dedicated Acres 320.00	13 Joint	or İnfill	Consolidation	Code 15	Order No.				

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



BURLINGTON OIL AND GAS COMPANY LP

SAN JUAN 27-4 UNIT #28C



SOE) SHALLOW ABOVE SE SE WIDE (OVERFLOW-3' SIDE DEEP œ 듬 RESERVE

PRIOR TO CONSTRUCTION. UNMARKED BURIED (2) WORKING DAYS C.C.I. SURVEY CONTRACTOR : PIPLINES OR (



EPA METHOD 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

ConocoPhillips	Project #	96052-0026
Reserve Pit	Date Reported	08-27-09
51372	Date Sampled	08-20-09
7737	Date Received	08-20-09
Soil	Date Extracted	08-25-09
Cool	Date Analyzed	08-26-09
Intact	Analysis Requested	8015 TPH
	Reserve Pit 51372 7737 Soil Cool	Reserve Pit Date Reported 51372 Date Sampled 7737 Date Received Soil Date Extracted Cool Date Analyzed

Parameter	Concentration (mg/Kg)	Det. Limit (mg/Kg)
Gasoline Range (C5 - C10)	30.3	0.2
Diesel Range (C10 - C28)	58.5	0.1
Total Petroleum Hydrocarbons	88.8	0.2

ND - Parameter not detected at the stated detection limit

References.

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996

Comments

San Juan 27-4 Unit 28C

Analyst

Review

Ph (505) 632-0615 Fr (800) 362-1879 Fx (505) 632-1865 lab@envirotech-inc com envirotech-inc com



EPA Method 8015 Modified Nonhalogenated Volatile Organics Total Petroleum Hydrocarbons

Quality Assurance Report

Client	QA/QC	Project #	N/A
Sample ID	08-26-09 QA/QC	Date Reported	08-27-09
Laboratory Number	51369	Date Sampled	N/A
Sample Matrix	Methylene Chloride	Date Received	N/A
Preservative	N/A	Date Analyzed	08-26-09
Condition	N/A	Analysis Requested	TPH

	I-Cal Date	i I-Cal RF:	C-Cal RF:	% Difference	Accept Range
Gasoline Range C5 - C10	05-07-07	1 0126E+003	1 0130E+003	0.04%	0 - 15%
Diesel Range C10 - C28	05-07-07	1 0424E+003	1 0428E+003	0.04%	0 - 15%

Blank Conc. (mg/L - mg/Kg)	Concentration	Detection Limit
Gasoline Range C5 - C10	ND	0.2
Diesel Range C10 - C28	ND	0.1
Total Petroleum Hydrocarbons	ND	0.2

Duplicate Conc. (mg/Kg)	Sample	Duplicate	% Difference	Accept Range
Gasoline Range C5 - C10	ND	ND	0.0%	0 - 30%
Diesel Range C10 - C28	ND	ND	0.0%	0 - 30%

	Spike Conc. (mg/Kg)	Sample	Spike Added	Spike Result	% Recovery	Accept: Range
*	Gasoline Range C5 - C10	ND	250	238	95.2%	75 - 125%
	Diesel Range C10 - C28	ND	250	244	97.6%	75 - 125%

ND - Parameter not detected at the stated detection limit

References

Method 8015B, Nonhalogenated Volatile Organics, Test Methods for Evaluating Solid Waste,

SW-846, USEPA, December 1996

Comments:

QA/QC for Samples 51329, 51369, 51372, 51385, 51386, 51393, 51394, 51404 and 51405.



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client	ConocoPhillips	Project #	96052-0026
Sample ID	Reserve Pit	Date Reported	08-27-09
Laboratory Number	51372	Date Sampled	08-20-09
Chain of Custody	7737	Date Received	08-20-09
Sample Matrix	Soil	Date Analyzed	08-26-09
Preservative	Cool	Date Extracted	08-25-09
Condition	Intact	Analysis Requested	BTEX

Parameter	Concentration (ug/Kg)	Det. Limit (ug/Kg)	
Benzene	9.2	0.9	
Toluene	81.6	1.0	
Ethylbenzene	53.6	1.0	
p,m-Xylene	454	1.2	
o-Xylene	161	0.9	
Total BTEX	759		

ND - Parameter not detected at the stated detection limit

Surrogate Recoveries:	Parameter	Percent Recovery
	Fluorobenzene	99.0 %
	1,4-difluorobenzene	99.0 %
	Bromochlorobenzene	99.0 %

References.

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996

Method 8021B, Aromatic Volatile Organics, Test Methods for Evaluating Solid Waste, SW-846,

USEPA, December 1996

Comments:

San Juan 27-4 Unit 28C

Analyst



EPA METHOD 8021 AROMATIC VOLATILE ORGANICS

Client	N/A	Project #	N/A
Sample ID	08-26-BT QA/QC	Date Reported	08-27-09
Laboratory Number	51369	Date Sampled	N/A
Sample Matrix	Soil	Date Received	N/A
Preservative	N/A	Date Analyzed	08-26-09
Condition	N/A	Analysis	BTEX

Calibration and Detection Limits (ug/L)	l-Cal.RF.	C-Cal RF Accept Rang	%Diff. je 0 - 15%	Blank Conc	Detect 4 Limit
Benzene	3 5755E+006	3 5826E+006	0.2%	ND	0.1
Toluene	3 2951E+006	3 3017E+006	0.2%	ND	0.1
Ethylbenzene	2 8689E+006	2 8747E+006	0.2%	ND	0.1
p,m-Xylene	7 4267E+006	7 4416E+006	0.2%	ND	0.1
o-Xylene	2 7792E+006	2 7847E+006	0.2%	ND	0.1

Duplicate Conc. (ug/Kg)	Sample Di	iplicate	%Diff,	Accept Range	Detect Limit
Benzene	8.0	7.6	5.0%	0 - 30%	0.9
Toluene	16.7	17.1	2.4%	0 - 30%	1.0
Ethylbenzene	20.1	19.4	3.5%	0 - 30%	1.0
p,m-Xylene	39.3	38.8	1.3%	0 - 30%	1.2
o-Xylene	23.9	23.1	3.3%	0 - 30%	0.9

Spike Conc. (ug/Kg)	Sample A	mount Spiked S	piked Sample	% Recovery	Accept Range
Benzene	8.0	50.0	57.2	98.6%	39 - 150
Toluene	16.7	50.0	66.2	99.3%	46 - 148
Ethylbenzene	20.1	50.0	68.6	97.9%	32 - 160
p,m-Xylene	39.3	100	130	93.5%	46 - 148
o-Xylene	23.9	50.0	72.2	97.7%	46 - 148

ND - Parameter not detected at the stated detection limit

References

Method 5030B, Purge-and-Trap, Test Methods for Evaluating Solid Waste, SW-846, USEPA,

December 1996

Method 8021B, Aromatic and Halogenated Volatiles by Gas Chromatography Using

Photoionization and/or Electrolytic Conductivity Detectors, SW-846, USEPA December 1996

Comments:

QA/QC for Samples 51329, 51369, 51372, 51385, 51386, 51393, 51394, 51396, 51404 and 51405.

Analyst

Client.	Conoco Phillips	Project #	96052-0026
Sample ID:	Reserve Pit	Date Reported	08-25-09
Laboratory Number.	51372	Date Sampled.	08-20-09
Chain of Custody No	7737	Date Received	08-20-09
Sample Matrix	Soil	Date Extracted.	08-21-09
Preservative:	Cool	Date Analyzed [.]	08-21-09
Condition [.]	Intact	Analysis Needed	TPH-418.1

		Det.
	Concentration	Limit
Parameter	(mg/kg)	(mg/kg)

Total Petroleum Hydrocarbons

276

11.0

ND = Parameter not detected at the stated detection limit

References:

Method 418.1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No. 4551, 1978

Comments

San Juan 27-4 Unit 28C

Analyst

Mostum Walt



EPA METHOD 418.1 TOTAL PETROLEUM HYROCARBONS QUALITY ASSURANCE REPORT

Client [.]	QA/QC	Project #:	N/A
		•	
Sample ID	QA/QC	Date Reported:	08-24-09
Laboratory Number	08-21-TPH.QA/QC 51239	Date Sampled [.]	N/A
Sample Matrix.	Freon-113	Date Analyzed [.]	08-21-09
Preservative:	N/A	Date Extracted ⁻	08-21-09
Condition.	N/A	Analysis Needed:	TPH

Calibration	I-Cal Date	C-Cal Date	I-Cal RF.	C-Cal RF.	% Difference	Accept Range	Ì
Total Marie Company and the time common marie of	08-03-09	08-21-09	1.380	1.490	8.0%	+/- 10%	-

Blank Conc. (mg/Kg)	Concentration	Detection Lim	it
TPH	ND	11.0	
Duplicate Conc. (mg/Kg)	Sample	Duplicate % Difference	Accept, Range
TPH	52 9	49.6 6.2%	+/- 30%

Spike Conc. (mg/Kg)	Sample	Spike Added	Spike Result	% Recovery	Accept Range
TPH	52.9	2,000	2,040	99.4%	80 - 120%

ND = Parameter not detected at the stated detection limit.

References¹

Method 418 1, Petroleum Hydrocarbons, Total Recoverable, Chemical Analysis of Water

and Waste, USEPA Storet No 4551, 1978.

Comments:

QA/QC for Samples 51239, 51369, 51372.

Analyst

Muslumy) (L



Chloride

Client.	ConocoPhillips	Project #:	96052-0026
Sample ID:	Reserve Pit	Date Reported:	08-27-09
Lab ID#·	51372	Date Sampled.	08-20-09
Sample Matrix.	Soil	Date Received:	08-20-09
Preservative:	Cool	Date Analyzed:	08-25-09
Condition:	Intact	Chain of Custody [.]	7737

Par	ameter	Concentration (mg/Kg)

Total Chloride 515

Reference: U.S.E P A., 4500B, "Methods for Chemical Analysis of Water and Wastes", 1983.

Standard Methods For The Examination of Water And Waste Water", 18th ed., 1992.

Comments. San Juan 27-4 Unit 28C.

Analyst

Mustle of Walders
Review

Submit To Appropri	riate District C	Office	State of New Mexico				Form C-105												
District I 1625 N French Dr	, Hobbs, NM	88240		Energy, Minerals and Natural Resources				July 17, 2008 1 WELL API NO.											
District II 1301 W Grand Av	enue, Artesia,	NM 88210		Oil Conservation Division						30-045-30589									
District III 1000 Rio Brazos Rd, Aztec, NM 87410 1220 South St. Francis Dr.							2 Type of Le		□ F	EE	⊠ r	ED/IND	LANI						
District IV 1220 S St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505							3 State Oil &	Gas				ED/IND	IAIN	-					
			<u> </u>	VE 0.01					_	1.00	-	SF-080671		ice sus		Maria No Supe	with a tribula	Language and the	
4 Reason for fil		ETION)K K	KEUUI	WP <u>L</u>	ETION RE	PU	XI ANL	<u>ر</u>	LUG	,	5 Lease Nam					ame	idia M	
☐ COMPLET		DT (Eill in E	ovan H	fl throug	.h.#21	for State and Fac	a 11/a11	c only)				SAN JUAN 27 6 Well Numb	<u>1</u> -4 U						
-		`						• /			.	28C	er						
#33, attach this a	nd the plat to										or_								
7 Type of Comp		WORKOVE	R □	DEEPEI	NING	□PLUGBACE	к 🗆	DIFFERE	N'	T RESERV	OIR	COTHER_							
8 Name of Opera Burlington Resou	ator											9 OGRID 14538							
10 Address of O		as Company	LP									11 Pool name	or W	ıldcat	-				_
12.Location	Unit Ltr	Section		Townsh	пр	Range	Lot		I	Feet from the	he	N/S Line	Fee	t from	the	E/W L	_ine	County	
Surface:					<u> </u>		ļ <u>.</u>		1										
13 Date Spudded	d 14 Date	TD Reach	ed	1 15 D:	ate Rio	Released .	ļ	116	I	Date Compl	eted	(Ready to Prod	uce)		17	Flevat	ions (DF	and RKB,	
				05/02/	/2009					·					RT	r, GR, e	tc)		
18 Total Measur	ed Depth of	Well		19 Pl	ug Bac	k Measured Dep	oth	20	'	Was Directi	iona	l Survey Made?		21	Туре	: Electri	ic and Ot	her Logs Run	
22 Producing Int	terval(s), of	this complet	on - T	op, Botte	om, Na	ame					-			<u> </u>		·			
23					CAS	ING REC	OR	D (Ren	<u></u>	rt all str	ine	os set in we	<u>-11)</u>						_
CASING SI	ZE	WEIGHT	LB /F			DEPTH SET				LE SIZE		CEMENTIN		CORL)	AN	MOUNT	PULLED	
															+				
															+		_ · · · · · · · · · · · · · · · · · · ·		
24					LINI	ER RECORD					25		HDT	NG R	ECC)DI)			
SIZE	TOP		BOT	TOM	LIN	SACKS CEM	ENT	SCREE	N		SIZ			EPTH			PACKI	ER SET	_
													\bot						
26 Perforation	record (inte	rval, size, ai	d num	nber)				27 AC	H	D. SHOT.	FR	ACTURE, CE	L MEI	NT. SC	OUE	EZE.	L ETC.		
	`			,						NTERVAL		AMOUNT A							_
							·					ļ							
28								ODUC											
Date First Produc	ction	Pr	oductio	on Meth	od (Fla	owing, gas lift, p	итріп	g - Size an	ıd	type pump))	Well Status	(Pro	d or S	hut-i	in)			
Date of Test	Hours T	ested	Chol	ke Sıze		Prod'n For Test Period		Oıl - Bb	ıl		Gas	s - MCF	w	ater - l	Bbl		Gas - C	Pil Ratio	
Flow Tubing Press	Casing I	Pressure	Calculated 24- Oil - Bbl Gas - MCF Water - Bbl Oil Gravity - API - (Corn Hour Rate						r)										
29 Disposition o	29 Disposition of Gas (Sold, used for fuel, vented, etc) 30 Test Witnessed By																		
31 List Attachme	ents													•					
32 If a temporary	y pit was use	ed at the well	, attac	h a plat v	with the	e location of the	tempo	orary pit										-	
33 If an on-site E	ourial was us		-						0.2	7 171000									
I hereby certij	fy that the	Latitude informati	36 592 on sh	own oi	n both	gitude 107 2234 In sides of this	forn	is true	92 ai	nd compl	ete	to the best o	f my	knov	vled	ge and	d belief		
Signature	_		/		Prin	nted ne Crystal T										201			
	E-mail Address crystal.tafoya@conocophillips.com																		

ConocoPhillips

Pit Closure Form:	
Date: 10/19/09	
Well Name: 21-4 28C	
Footages:	Unit Letter:
Section:, TN, RW, County: _	State:
Contractor Closing Pit: 124-c	-
Construction Inspector: Size Smith	Date: 10/20/09
Inspector Signature:	

Tafoya, Crystal

From:

Bonilla, Amanda

Sent:

Monday, October 12, 2009 9 12 AM

To:

Brandon Powell@state nm us, Mark Kelly, Robert Switzer, Sherrie Landon

Cc:

'bko@digii net', Aztec Excavation; Elmer Perry, Faver Norman (faverconsulting@yahoo com),

Jared Chavez, Bassing, Kendal R.; Scott Smith, Silverman, Jason M, Smith Eric

(sconsulting eric@gmail.com), 'Steve McGlasson', Terry Lowe; Becker, Joey W; Bonilla, Amanda, Bowker, Terry D, Gordon Chenault, GRP SJBU Production Leads, Hockett, Christy R, Johnson, Kirk L; Kennedy, Jim R, Lopez, Richard A; Nelson, Terry J, O'Nan, Mike J, Peace, James T, Pierce, Richard M; Poulson, Mark E; PTRRC, Richards, Brian, Smith, Randall O, Spearman, Bobby E; Stamets, Steve A, Thacker, LARRY; Work, Jim A

Subject:

Reclamation Notice - San Juan 27-4 Unit 28C

Attachments:

San Juan 27-4 unit 28C.PDF; Picture (Metafile), Picture (Metafile)

AZTEC EXCAVATION will move a tractor to the <u>San Juan 27-4 Unit 28C</u> on <u>Wednesday Oct. 14th</u> to start reclamation of PIT only.

Please contact Eric Smith (608.1387) if you have any questions or need further assistance.



San Juan 27-4 unit 28C.PDF

Burlington Resources Well- Network #: 10158811

Rio Arriba County, NM

SAN JUAN 27-4 UNIT 28C - FOREST surface / FOREST minerals

Twin: San Juan 27-4 Unit 28A

910' FNL, 1870' FWL

SEC. 11, T27N, R04W

Unit Letter 'C'

BH: NE1/4SW1/4 SEC. 11, T27N, R04W

Lease #: USA SF-080671-A

Latitude: 36° 35 min 32.34480 sec N (NAD 83)

Longitude: 107° 13 min 24.57840 sec W (NAD83)

Elevation: 7156'

API#: 30-039-30589



Amanda L. Bonilla

SAN JUAN 27-4 UNIT #28C LATITUDE 36° 35 MIN. 32.34480 SEC. N (NAD 83) LONGITUDE 107° 13 MIN. 24.57840 SEC. W (NAD 83) UNIT C SEC 11 T27N RO4W BH: NE1/4 SW1/4 SEC 11 T27N RO4W 910' FNL 1870' FWL / API#30-039-30589 LEASE# USA SF-080671-A ELEV.7156' RIO ARRIBA COUNTY, NEW MEXICO EMERGENCY CONTACT: 1-505-324-5170



WELL PAD SAFETY AND ENVIRONMENTAL CHECK LIST

WELL NAME: San Juan 27-4 Unit 28C

API#: 30-039-30589

DATE	INSPECTOR	SAFETY CHECK	LOCATION CHECK	PICTURES TAKEN	COMMENTS
5/8/09	Jared Chavez	Х	Х		Location is good. JEG
5/21/09	Jared Chavez	Х	Х		Location is good. JEG
5/29/09	Jared Chavez	Χ	Х		Location is good. JEG
7/30/09	Elmer Perry	Χ	Х		Some culverts were smashed
9/8/09	Elmer Perry	Х	X		Sign on location

DATE: 6/19/12

WELL NAME: SAN JUAN 27-4 UNIT 28C

API# 30-039-30589 PERMIT #: 5196

MISSING DATA: PICTURES OF RECLAMATION ATTACHED: PICTURES OF RECLAMATION

RCVD JUN 22'12 OIL CONS. DIV.

DIST. 3



