




NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6170 FAX: (505) 334-6170
[http://emmrnd.state.nm.us/ocd/District III/district](http://emmrnd.state.nm.us/ocd/District%20III/district)



BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12-6-04 Operator H.E.C. Petroleum Inc. API #30-0 45-22382
Property Name Yager Well No. #2 MW Location: Unit B Section 20 Township 32N Range 6W
Pressure (Shut-In or Producing) Tubing 87 Intermediate N/A Casing 225 Bradenhead 36

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED		INTERMEDIATE FLOWED	
	INTERMEDIATE	CASING				
5 minutes	<u>N/A</u>	TP <u>87</u> CP <u>225</u>	Steady Flow		<u>N/A</u>	
10 minutes		<u>87</u> <u>225</u>	Surges			
15 minutes		<u>87</u> <u>225</u>	Down to Nothing	<u>X</u>		
20 minutes			Nothing			
25 minutes			Gas	<u>X</u>		
30 minutes			Gas & Water			
			Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

REMARKS:

Bradenhead flowed down to nothing in 9 seconds through
a 1" valve

By Russ Knight Witness _____
Measurement Tech.
(Position)