

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
Aztec District Office
1000 Rio Brazos Road
Aztec NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://nemrds.state.nm.us/ocd/District III/3district.htm](http://nemrds.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-8-04 Operate PATINA SAN JUAN, INC. API# 30-039-06750

Property Name HURON Well No. 3 Location: Unit A Section 2 Twp 26N Range 04W

Pressure (Shut-in or Producing) _____ Tubing 125 Intermediate N/A Casing 160 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>N/A</u>	<u>160</u>	Steady Flow	
10 minutes		<u>160</u>	Surges	
15 minutes		<u>160</u>	Down to Nothing	
20 minutes			Nothing	<u>N/A</u>
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By Larry Bingham Witness _____
Pumper
(Position)

