



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-23-04 Operator MALLON OIL API #30-0 39-24167

Property Name JIC 458 Well No. 355 Location: Unit 4 Section 7 Township 30N Range 3W

Well Status(Shut-In or Producing) Tubing X Intermediate Casing Bradenhead

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u> </u>	<u> </u>	Steady Flow <u> </u>	
10 minutes	<u> </u>	<u> </u>	Surges <u> </u>	
15 minutes	<u> </u>	<u> </u>	Down to Nothing <u> </u>	
20 minutes	<u> </u>	<u> </u>	Nothing <u> </u> <u>X</u>	
25 minutes	<u> </u>	<u> </u>	Gas <u> </u>	
30 minutes	<u> </u>	<u> </u>	Gas & Water <u> </u>	
			Water <u> </u>	

If bradenhead flowed water, check all of the descriptions that apply below:


CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

By [Signature]
Plant Foreman
(Position)

Witness _____



Unable to operate root valves on BH - probably not
ST for 24 hrs