



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3district.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-28-04 Operator MAKON API #30-0 39-24305

Property Name JIC 459 Well No. 8-55 Location: Unit D Section 17 Township 30N Range 3W

Well Status (Shut-In or Producing) Tubing _____ Intermediate _____ Casing X Bradenhead _____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>—</u>	<u>30</u>	Steady Flow _____	
10 minutes	<u>—</u>	<u>32</u>	Surges _____	
15 minutes	<u>—</u>	<u>32</u>	Down to Nothing _____	
20 minutes	<u>—</u>	<u>33</u>	Nothing <u>X</u> _____	
25 minutes	<u>—</u>	<u>33</u>	Gas _____	
30 minutes	<u>—</u>	<u>34</u>	Gas & Water _____	
			Water _____	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____


5 MINUTE SHUT-IN BRADENHEAD X INTERMEDIATE _____

REMARKS:

By

Lang Shup
Plant Foreman
(Position)

Witness _____



BH Surface valve is dug out - unknown if there is another valve