



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-28-04 Operator MALLO API #30-0 39-24305

Property Name JIC. 459 Well No. 80A Location: Unit D Section 17 Township 30N Range 3W

Well Status (Shut-In) or Producing) Tubing _____ Intermediate _____ Casing _____ Bradenhead _____

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes		<u>412</u>	Steady Flow	
10 minutes		<u>u</u>	Surges	
15 minutes		<u>u</u>	Down to Nothing	
20 minutes		<u>u</u>	Nothing	<u>X</u>
25 minutes		<u>u</u>	Gas	
30 minutes		<u>u</u>	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____


5 MINUTE SHUT-IN BRADENHEAD X INTERMEDIATE _____

REMARKS:

well 8-2

By [Signature] Witness _____

Plant Foreman
(Position)



Dirt + gravel packed around valve handle. Valve was not
opened

pic 75