



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-3-12 Operator Four Star API #30-0 45-29401
Property Name Ed State Com Well No. 2 Location: Unit Section 32 Township 30 Range 11
Well Status (Shut-In or Producing) Initial PSI: Tubing 16.1 Intermediate N/A Casing 16.5 Bradenhead 11

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		16		
10 min	0		16		
15 min	0		16		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
DIST. 3	
Steady Flow	
Surges	OIL CONS. DIV.
Down to Nothing	RCVD JUL 3'12
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

dead at 3 seconds

By Randy Calco Jr
Culder servicer
(Position)

Witness

Marcia Kuehling

E-mail address