

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NII 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3@stric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test $9-1-09$	Operator_	Richardson	API #30-0	45-	30392
Property Name wF Fed 27	_Well Nol	Location: Unit G	Section_27To	wnship_	Range 14 u
Well Status(Shut-In or Producing)	Tubing 60	Intermediate Casi	ng 21 Bran	ndenhead	0
OPEN BRADENHEAD AND INTI	ERMEDIATE TO	O ATMOSPHERE INDIV	VIDUALLY FO	R 15 MIN	UTES EACH
PRESSURES: TIME INTERMEDIATE	CASING		BRADENHEA FLOWED	D i	INTERMEDIATE FLOWED
5 minutes		Steady Flow			
10 minutes		Surges			
15 minutes		Down to Nothin	g		
20 minutes		Nothing			
25 minutes		Gas			
30 minutes	•	Gas & Water			•
		Water			
If bradenhead flowed water, check all o	f the descriptions	s that apply below:		·	
CLEARFRESH			CK		
5 MINUTE SHUT-IN BRADENHEA	D	INTERMEDIATE			
REMARKS:					
			· ·		
By Zuki	Witne	ess			
ops mgr			***************************************		
(Position)					