

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170

http://emmrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test_	4-1-04	Operator	Richardson	_API #30-0_ <i>45</i>	- 30689
Property Nam	newf Fed 27	_Well No2	Location: Unit S	ection_27Townsh	ip 30 Range_i≠v
Well Status(S	Shut-In or Producing)	Tubing 45	Intermediate Casin	ng 2.2 Brandenh	nead_O
OPEN BRA	DENHEAD AND INT	ERMEDIATE T	O ATMOSPHERE INDIV	IDUALLY FOR 15	MINUTES EACH
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow		
10 minutes					
15 minutes			Down to Nothing	g	
20 minutes			Nothing		
25 minutes			Gas	•	
30 minutes	· · ·	*	Gas & Water	•	•
			Water		
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE					
REMARKS:					
	<i>6</i> ·				
By Z.	n h 's Mgr	Witn	ess	<del></del>	
(Posit					