



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrmd.state.nm.us/ocd/District III/district.htm](http://emrmd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-28-12 Operator CHEVRON MIDCONTINENT, LP API # 30-045-23196
Property Name MONTOYA 25 #1 Well No. #1 Location: Unit Section -25 Township -32N Range -13W
Well Status (Shut-In or Producing) Initial PSI: Tubing 111.8 Intermediate Casing 10.8 Bradenhead 0.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	X	10.8		
10 min	0	X	10.8		
15 min	0	X	10.8		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

Oil Cons. Div
District III

JUL 05 2012

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.1 INTERMEDIATE

REMARKS:

By Randy Caldeira
Caldeira Services
(Position)

Witness _____

E-mail address Randy.Caldeira@caldeira-services.com