



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrds.state.nm.us/ocd/District III/district.htm](http://emrds.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-28-12 Operator CHEVRON MIDCONTINENT, LP API # 30-030-045-33425

Property Name RIPLEY 26 #6 Well No. #6 Location: Unit Section -26 Township -32N Range -13W

Well Status (Shut-In or Producing) Initial PSI: Tubing 58.1 Intermediate X Casing 6.6 Bradenhead 11.8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead	INTERM	Int	Csg
TIME					
5 min	<u>0</u>	<u>V</u>	<u>6.3</u>		
10 min	<u>0</u>	<u>Y</u>	<u>6.3</u>		
15 min	<u>0</u>	<u>Y</u>	<u>6.3</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>X 5 sec</u>	
Nothin	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

Oil Cons. Div
District III

JUL 05 2012

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0.2

INTERMEDIATE

REMARKS:

By Randy Caldeira
Caldeira sensors
(Position)

Witness

E-mail address Randy.Caldeira@sensers