



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUN 27 '12

OIL CONS. DIV.

DIST. 3

Date of Test 6-22-12 Operator DS Simmons API #30-0 45-23623

Property Name Blackrock D Cover No. 1E Location: Unit N Section 20 Township 26N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 24 Intermediate — Casing 24 Bradenhead ⊖

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	⊖		24		
10 min	⊖		24		
15 min	⊖		24		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD ⊖

INTERMEDIATE —

REMARKS:

By Scott Elmer
Field Tech.
(Position)

Witness —

E-mail address —