



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnrd.state.nm.us/ocd/District III/3distnc.htm>

RCVD JUN 27 '12
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test June 6, 2012 Operator Koch Exploration Company, LLC API #30-045-26002

Property Name Dryden Well No. 2E Location: Unit I Section 22 Township 28N Range 08W

Well Status(Shut-In or Producing) Initial PSI: Tubing 107 Intermediate 4 Casing 223 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	4	223		
10 min	0	4	223		
15 min	0	4	223		
20 min	0			0	223
25 min	0			0	223
30 min	0			0	223

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	X
Nothing		
Gas	X	X
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

By Kenneth Cagle
Operations Technician
(Position)

Witness _____

E-mail address CagleK@Kochind.com or Johnso4d@Kochind.com