



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

RCVD JUN 28 '12
OIL CONS. DIV.
DIST. 3

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-25-12 Operator CHEVRON MIDCONTINENT, LP API # 30-030-045-32342

Property Name O'SHEA 3 #3 Well No. #3 Location: Unit Section -3 Township -31N Range -13W

Well Status (Shut-In or Producing) Initial PSI: Tubing 2 Intermediate X Casing 10 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>X</u>	<u>10</u>		
10 min	<u>0</u>	<u>X</u>	<u>10.4</u>		
15 min	<u>0</u>	<u>X</u>	<u>10.7</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Randy Calder
Calder services
(Position)

Witness

E-mail address Randy.C@calder-services.com