

(Position)

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Data of Tost	4-6-04	Omorata	- lideachean	^ ADI#200 <b>♣</b>	5- 30654
Date of Test_		Operato	or Michael as on	AF1#30-0/_	, , , , , ,
Property Nan	ne Navajo P	<u></u>	2 Location: Unit H	Section 14 Townsh	nip 29 Range 14 v
Well Status(S	Shut-In or Producin	g) Tubing 3	Intermediate Casi	ing 49 Brandenl	nead 0
OPEN BRA	ADENHEAD AND I	NTERMEDIATE	TO ATMOSPHERE INDI	VIDUALLY FOR 15	MINUTES EACH
TIME	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothin	1g	
20 minutes			Nothing		
25 minutes			Gas		678
30 minutes			Gas & Water	AP	4
			Water		2004
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE					
REMARKS:					
					· · · · · · · · · · · · · · · · · · ·
		<u>,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,</u>			
				8.1	
D	2 4				
By	2 Mar	Wi	tness		
ץ ט	> M.9 r				