

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test $\frac{4-6-07}{}$ Operator	Richardson API	#30-0_45	- 30 992
Property Name Ropco 16 Well No. 4 Location: Unit N Section 16 Township 29 Range 17 u			
Well Status(Shut-In or Producing) Tubing 37 Intermediate Casing 22 Brandenhead O			
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH			
PRESSURES: TIME INTERMEDIATE CASING		DENHEAD DWED	INTERMEDIATE FLOWED
5 minutes	Steady Flow		
10 minutes	Surges		
15 minutes	Down to Nothing		
20 minutes	Nothing		
25 minutes	Gas		
30 minutes	· Gas & Water		10. 1 27.
	Water	(31)	
If bradenhead flowed water, check all of the descriptions that apply below: CLEAR FRESH SALTY SULFUR BLACK			
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE			
REMARKS:			
·			
By Zuh' Witness			
OPS Mgr (Position)			