



ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-29-04 Operator CDX Rio, LLC API # 3003906248

Property Name Jicarilla Cont 155 #003 Location: Unit F Section 32 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 40" Intermediate _____ Casing 80" Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Flow Description	Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor			
5 minutes	<u>0</u>					Steady Flow		
10 minutes						Surges		
15 minutes						Down to Nothing		
20 minutes						No Flow <u>X</u>		
25 minutes						Gas		
30 minutes						Gas and Water		
5 minute St						Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

EMARKS:

Danell Spear
Tech

(Position)

Witness

Harry W. Ransom T.P.S.

NMOCD Test Area: