



NEW MEXICO DEPARTMENT OF ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-26-04 Operator CDX Rio, LLC API # 3003906326

Property Name Jicarilla Cont 155 #009 Location: Unit C Section 30 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 40 Intermediate _____ Casing 80 Bradenhead 6

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH- Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	<u>B</u>											
10 minutes												
15 minutes												
20 minutes												
25 minutes												
30 minutes												
5 minute St												

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:



Daniel Spier
Tech

Witness _____

(Position)

NMOCD Test Area: