



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

Oil & CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-30-04 Operator CDX Rio LLC API # 3003908139

Property Name Jicarilla C-4 Location: Unit F Section 24 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 95 Intermediate Casing 130 Bradenhead 8

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH- Blowdown	Casing- Monitor	Intermediate- Monitor	Intermediate- Blowdown	Casing- Monitor		
5 minutes						Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing <u>1 Sec</u>	
20 minutes						No Flow	
25 minutes						Gas <u>X</u>	
30 minutes						Gas and Water	
5 minute St						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead ○ Intermediate

REMARKS:

✓ James Simpson
TPS. Tech

(Position)

Witness

Harry Whitson T.P.S.

NMOCD Test Area:

