



OIL AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-27-04 Operator CDX Rio, LLC API # 3003922344

Property Name Jicarilla cont 155 #205 Location: Unit C Section 29 Township 26 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 70th Intermediate _____ Casing 80th Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	<u>0th</u>											
10 minutes												
15 minutes												
20 minutes												
25 minutes												
30 minutes												
5 minute St												

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

EMARKS:



Witness _____

Danell Spear
Tech
(Position)

NMOCD Test Area: