

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENTOIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410(505) 334-6178 FAX: (505) 334-6170
<http://www.nrd.state.nm.us/ocd/DistrictIII/3district.htm>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)


Date of Test 10-13-04 Operator ROBERT L. BAYLESS, PRODUCER LLC API #30-0 39-06213

Property Name Bolack Well No. 3 Location: Unit P Section 31 Township 26N Range 7W

Well Status (Shut-In or Producing) Producing Tubing 30 Intermediate 1 Casing 50 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>0</u>	<u>55</u>	Steady Flow	<u>NO</u>	
10 minutes	<u>0</u>	<u>55</u>	Surges	<u>NO</u>	
15 minutes	<u>0</u>	<u>55</u>	Down to Nothing		
20 minutes	<u>0</u>	<u>56</u>	Nothing	<u>X</u>	
25 minutes	<u>0</u>	<u>56</u>	Gas		
30 minutes	<u>0</u>	<u>56</u>	Gas & Water		
			Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Looked Good

By

Robert L. Bayless

Witness

(Position)