

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT


Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**  
(Submit 2 copies to above address)

Date of Test 5-26-04 Operator Dugan Production Corp. API # 30-039-25745  
Property Name MONA LISA Well No. 2 Location: Unit J Section 14 Township 26N Range 07W  
Well Status(Shut-In or Producing) Tubing 40 Intermediate 1 1/4 Casing 20 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>20</u>	Steady Flow		
10 minutes		<u>20</u>	Surges		
15 minutes		<u>20</u>	Down to Nothing		
20 minutes		<u>20</u>	Nothing	✓	
25 minutes		<u>20</u>	Gas		
30 minutes		<u>20</u>	Gas & Water		
			Water		



**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN** BRADENHEAD 0 INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Bill Wilson Witness \_\_\_\_\_

29 Switcher  
(Position)