



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(808) 334-6178 FAX: (505) 334-6170
<http://emrmd.state.nm.us/ocd/District10/3distric.htm>

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 9-8-04 Operator Pace API #30-0 29-06739

Property Name Rincon Well No. 130 Location: Unit A Section 6 Township 26N Range 6W

Well Status(Shut-In or Producing) Tubing 42 Intermediate 79 Casing 79 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>4</u>	<u>79</u>	Steady Flow	
10 minutes	<u>2</u>	<u>77</u>	Surges	
15 minutes	<u>TSTM</u>	<u>72</u>	Down to Nothing	<u>X</u>
20 minutes	<u>TSTM</u>	<u>72</u>	Nothing	<u>X</u>
25 minutes	<u>TSTM</u>	<u>72</u>	Gas	<u>X</u>
30 minutes	<u>TSTM</u>	<u>72</u>	Gas & Water	
			Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

Inter mediate flowed for 10 minutes last 5 minutes Blow to nothing.

By A. J. Pace

Witness Jan Carey

Pace
(Position)

