



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10/12/04 Operator CDX Gas API # 3003906481
Property Name Jicarilla A-1 Location: Unit _____ Section 18 Township 26N Range 5W
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 176 Intermediate 56 Casing 177 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	<u>0</u>	<u>179</u>			<u>179</u>		
10 minutes		<u>181</u>			<u>181</u>		
15 minutes		<u>182</u>			<u>182</u>		X
20 minutes						X	
25 minutes							X
30 minutes							
5 minute SI	<u>0</u>			<u>0</u>			

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

Intermediate blew down in 10 seconds



Dwaine Harrison
Field Tech

(Position)

Witness _____

NMOCD Test Area: C