

NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10/15/04 Operator Eddie API # _____
Property Name Jicarilla C-2 Location: Unit _____ Section 14 Township 26N Range 5W
(Well Name and Number)
Pressure (Shut-in or Producing) _____ Tubing 48 Intermediate 92 Casing 190 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	0	190	92	92	190	No	yes
10 minutes			0	0	140	no	yes
15 minutes			0	0	105	yes	VAPORS
20 minutes			0	0	102		
25 minutes			0	0	100	Gas	yes
30 minutes			0	0	100	Gas and Water	NO
5 minute SI			10	10	100	Water	NO

If bradenhead flowed water, check all of the descriptions that apply below:


Clear N/A Fresh N/A Salty N/A Sulfur N/A Black N/A

REMARKS:

Intermediate did not blow down -
Bradenhead had little gas blew down to nothing
Intermediate blew down in 10 min down to nothing

Witness _____

(Position)



NMOCD Test Area: C